




REPORT No. : SZ19100071W02



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.  
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,  
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. ChinaTel: 86-755-36698555 Fax: 86-755-36698525  
Http://www.morlab.cn E-mail: service@morlab.cn




## Band2 / 15MHz / Low CH / QPSK




## Band2 / 15MHz / Low CH / 16QAM




## Band2 / 15MHz / Low CH / 64QAM




## Band2 / 15MHz / Mid CH / QPSK



## Band2 / 15MHz / Mid CH / 16QAM



## Band2 / 15MHz / Mid CH / 64QAM





## Band2 / 15MHz / High CH / QPSK



## Band2 / 15MHz / High CH / 16QAM




## Band2 / 15MHz / High CH / 64QAM




## Band2 / 20MHz / Low CH / QPSK




## Band2 / 20MHz / Low CH / 16QAM




## Band2 / 20MHz / Low CH / 64QAM







## Band4 / 1.4MHz / Low CH / QPSK




## Band4 / 1.4MHz / Low CH / 16QAM




## Band4 / 1.4MHz / Low CH / 64QAM



## Band4 / 1.4MHz / Mid CH / QPSK



## Band4 / 1.4MHz / Mid CH / 16QAM



## Band4 / 1.4MHz / Mid CH / 64QAM







## Band4 / 1.4MHz / High CH / QPSK




## Band4 / 1.4MHz / High CH / 16QAM




## Band4 / 1.4MHz / High CH / 64QAM




## Band4 / 3MHz / Low CH / QPSK




## Band4 / 3MHz / Low CH / 16QAM



## Band4 / 3MHz / Low CH / 64QAM








REPORT No. : SZ19100071W02

## Band4 / 5MHz / Low CH / QPSK




## Band4 / 5MHz / Low CH / 16QAM




## Band4 / 5MHz / Low CH / 64QAM



## Band4 / 5MHz / Mid CH / QPSK



## Band4 / 5MHz / Mid CH / 16QAM



## Band4 / 5MHz / Mid CH / 64QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.  
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,  
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. ChinaTel: 86-755-36698555 Fax: 86-755-36698525  
Http://www.morlab.cn E-mail: service@morlab.cn




REPORT No. : SZ19100071W02


### Band4 / 5MHz / High CH / QPSK




### Band4 / 5MHz / High CH / 16QAM




### Band4 / 5MHz / High CH / 64QAM



### Band4 / 10MHz / Low CH / QPSK




### Band4 / 10MHz / Low CH / 16QAM



### Band4 / 10MHz / Low CH / 64QAM








## Band4 / 15MHz / Low CH / QPSK




## Band4 / 15MHz / Low CH / 16QAM




## Band4 / 15MHz / Low CH / 64QAM




## Band4 / 15MHz / Mid CH / QPSK



## Band4 / 15MHz / Mid CH / 16QAM



## Band4 / 15MHz / Mid CH / 64QAM







## Band4 / 15MHz / High CH / QPSK




## Band4 / 15MHz / High CH / 16QAM




## Band4 / 15MHz / High CH / 64QAM



## Band4 / 20MHz / Low CH / QPSK



## Band4 / 20MHz / Low CH / 16QAM



## Band4 / 20MHz / Low CH / 64QAM







## Band4 / 20MHz / Mid CH / QPSK




## Band4 / 20MHz / Mid CH / 16QAM




## Band4 / 20MHz / Mid CH / 64QAM



## Band4 / 20MHz / High CH / QPSK



## Band4 / 20MHz / High CH / 16QAM



## Band4 / 20MHz / High CH / 64QAM

