FCC RF Test Report

APPLICANT : CT Asia

EQUIPMENT: Mobile phone

BRAND NAME : BLU

MODEL NAME : Sport 4.5

FCC ID : YHLBLUSPORT45

STANDARD : FCC Part 15 Subpart C §15.247

CLASSIFICATION : (DSS) Spread Spectrum Transmitter

The product was received on Jul. 30, 2014 and testing was completed on Sep. 07, 2014. We, SPORTON INTERNATIONAL (KUNSHAN) INC., would like to declare that the tested sample has been evaluated in accordance with the test procedures and has been in compliance with the applicable technical standards.

The test results in this report apply exclusively to the tested model / sample. Without written approval of SPORTON INTERNATIONAL (KUNSHAN) INC., the test report shall not be reproduced except in full.

Reviewed by: Joseph Lin / Supervisor

Approved by: Jones Tsai / Manager

SPORTON INTERNATIONAL (KUNSHAN) INC.

No. 3-2, PingXiang Road, Kunshan, Jiangsu Province, P. R. C.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 1 of 70
Report Issued Date : Sep. 17, 2014

Testing Laboratory 2627

Report No.: FR473002A

Report Version : Rev. 01

TABLE OF CONTENTS

| RE | VISIO | N HISTORY | 3 |
|----|-------|---|----|
| SU | MMAF | RY OF TEST RESULT | 4 |
| 1 | GENI | ERAL DESCRIPTION | 5 |
| | 1.1 | Applicant | 5 |
| | 1.2 | Manufacturer | |
| | 1.3 | Product Feature of Equipment Under Test | |
| | 1.4 | Product Specification subjective to this standard | |
| | 1.5 | Modification of EUT | |
| | 1.6 | Testing Location | 6 |
| | 1.7 | Applicable Standards | 7 |
| 2 | TEST | CONFIGURATION OF EQUIPMENT UNDER TEST | 8 |
| | 2.1 | Descriptions of Test Mode | 8 |
| | 2.2 | Test Mode | 9 |
| | 2.3 | Connection Diagram of Test System | 10 |
| | 2.4 | Support Unit used in test configuration and system | 11 |
| | 2.5 | EUT Operation Test Setup | 11 |
| | 2.6 | Measurement Results Explanation Example | 12 |
| 3 | TEST | RESULT | 13 |
| | 3.1 | Number of Channel Measurement | 13 |
| | 3.2 | Hopping Channel Separation Measurement | |
| | 3.3 | Dwell Time Measurement | |
| | 3.4 | 20dB Bandwidth Measurement | |
| | 3.5 | Peak Output Power Measurement | |
| | 3.6 | Conducted Band Edges Measurement | |
| | 3.7 | Conducted Spurious Emission Measurement | |
| | 3.8 | Radiated Band Edges and Spurious Emission Measurement | |
| | 3.9 | AC Conducted Emission Measurement | |
| | 3.10 | Antenna Requirements | 68 |
| 4 | LIST | OF MEASURING EQUIPMENT | 69 |
| 5 | UNC | ERTAINTY OF EVALUATION | 70 |
| AP | PEND | IX A. SETUP PHOTOGRAPHS | |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45

REVISION HISTORY

| REPORT NO. | VERSION | DESCRIPTION | ISSUED DATE |
|------------|---------|-------------------------|---------------|
| FR473002A | Rev. 01 | Initial issue of report | Sep. 17, 2014 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 3 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

SUMMARY OF TEST RESULT

| Report Section | FCC Rule | Description | Limit | Result | Remark |
|-------------------|-----------------------|--|----------------------------|--------|--|
| 3.1 | 15.247(a)(1) | Number of Channels | ≥ 15Chs | Pass | - |
| 3.2 | 15.247(a)(1) | Hopping Channel Separation | ≥ 2/3 of 20dB BW | Pass | - |
| 3.3 | 15.247(a)(1) | Dwell Time of Each Channel | ≤ 0.4sec in 31.6sec period | Pass | - |
| 3.4 | 15.247(a)(1) | 20dB Bandwidth | NA | Pass | - |
| 3.5 | 15.247(b)(1) | Peak Output Power | ≤ 125 mW | Pass | - |
| 3.6 | 15.247(d) | Conducted Band Edges | ≤ 20dBc | Pass | - |
| 3.7 | 15.247(d) | Conducted Spurious Emission | ≤ 20dBc | Pass | - |
| 3.8 | 15.247(d) | Radiated Band Edges and Radiated Spurious Emission | 15.209(a) & 15.247(d) | Pass | Under limit 10.67 dB at 30.000 MHz |
| 3.9 | 15.207 | AC Conducted Emission | 15.207(a) | Pass | Under limit 16.09 dB at 0.160 MHz |
| 3.10 | 15.203 & 15.247(b) | Antenna Requirement | N/A | Pass | - |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 4 of 70 Report Issued Date : Sep. 17, 2014

Report No. : FR473002A

Report Version : Rev. 01

General Description 1

1.1 Applicant

CT Asia

Unit 01, 15/F, Seaview Centre, 139-141 Hoi bun road, Kwun Tong, Kowloon, Hongkong

1.2 Manufacturer

Ragentek Technology Group

Building D10-D11, No. 58-60, Lane 3188, Xiupu Road, PuDong District, Shanghai, P.R.C.

1.3 Product Feature of Equipment Under Test

| Product Feature | | | | |
|---------------------------------|---|--|--|--|
| Equipment | Mobile phone | | | |
| Brand Name | BLU | | | |
| Model Name | Sport 4.5 | | | |
| FCC ID | YHLBLUSPORT45 | | | |
| EUT supports Radios application | GSM/GPRS/WCDMA/HSPA/HSPA+(Downlink Only)/ WLAN 2.4GHz 802.11b/g/n HT20 Bluetooth v3.0 +EDR/ Bluetooth v4.0 LE | | | |
| HW Version | v1.0 | | | |
| SW Version | BLU_S430_V07_GENERIC | | | |
| EUT Stage | Pre-Production | | | |

Remark: The above EUT's information was declared by manufacturer. Please refer to the specifications or user's manual for more detailed description.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 5 of 70 Report Issued Date: Sep. 17, 2014

Report No.: FR473002A

Report Version : Rev. 01

1.4 Product Specification subjective to this standard

| Product Specification subjective to this standard | | | | |
|---|--|--|--|--|
| Tx/Rx Frequency Range | 2402 MHz ~ 2480 MHz | | | |
| Number of Channels | 79 | | | |
| Carrier Frequency of Each Channel | 2402+n*1 MHz; n=0~78 | | | |
| Maximum Output Power to Antenna | Bluetooth BR(1Mbps) : 5.42 dBm (0.00348 W) Bluetooth EDR (2Mbps) : 5.09 dBm (0.00323 W) Bluetooth EDR (3Mbps) : 5.06 dBm (0.00321 W) | | | |
| Antenna Type/ Gain | PIFA Antenna with gain 3 dBi | | | |
| Type of Modulation | Bluetooth BR (1Mbps) : GFSK Bluetooth EDR (2Mbps) : π /4-DQPSK Bluetooth EDR (3Mbps) : 8-DPSK | | | |

1.5 Modification of EUT

No modifications are made to the EUT during all test items.

1.6 Testing Location

| Test Site | SPORTON INTERNATIONAL (KUNSHAN) INC. | | | | |
|--------------------|--|-----------|---------|----------------------|--|
| | No. 3-2, PingXiang Road, Kunshan, Jiangsu Province, P.R.C. | | | | |
| Test Site Location | TEL: +86-0512-5790-0158 | | | | |
| | FAX: +86-0512-5790-0958 | | | | |
| Test Site No. | Sporton Site No. FCC Registration | | | FCC Registration No. | |
| rest site No. | TH01-KS | 03CH01-KS | CO01-KS | 149928 | |

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 6 of 70 Report Issued Date : Sep. 17, 2014

Report No.: FR473002A

Report Version : Rev. 01

1.7 Applicable Standards

According to the specifications of the manufacturer, the EUT must comply with the requirements of the following standards:

- FCC Part 15 Subpart C §15.247
- FCC Public Notice DA 00-705
- ANSI C63.4-2003

Remark:

- **1.** All test items were verified and recorded according to the standards and without any deviation during the test.
- 2. This EUT has also been tested and complied with the requirements of FCC Part 15, Subpart B, recorded in a separate test report.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 7 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

Test Configuration of Equipment Under Test 2

Descriptions of Test Mode

Preliminary tests were performed in different data rates and recorded the RF output power in the following table:

| | | Bluetooth RF Output Power | | | | |
|----------|-----------|---------------------------|------------------------|----------|--|--|
| Channel | Eroguenov | | Data Rate / Modulation | | | |
| Chamilei | Frequency | GFSK | π/4-DQPSK | 8-DPSK | | |
| | | 1Mbps | 2Mbps | 3Mbps | | |
| Ch00 | 2402MHz | 3.45 dBm | 3.18 dBm | 3.21 dBm | | |
| Ch39 | 2441MHz | 5.22 dBm | 4.89 dBm | 4.91 dBm | | |
| Ch78 | 2480MHz | <mark>5.42</mark> dBm | 5.09 dBm | 5.06 dBm | | |

Remark:

- 1. All the test data for each data rate were verified, but only the worst case was reported.
- 2. The data rate was set in 1Mbps for all the test items due to the highest RF output power.
- a. The EUT has been associated with peripherals and configuration operated in a manner tended to maximize its emission characteristics in a typical application. Frequency range investigated: conduction (150 kHz to 30 MHz), radiation (9 kHz to the 10th harmonic of the highest fundamental frequency or to 40 GHz, whichever is lower). Pre-scanned tests, X, Y, Z in three orthogonal panels, and different data rates were conducted to determine the final configuration (Y plane as worst plane) from all possible combinations, and the worst mode of radiated spurious emissions is Bluetooth 1Mbps mode, and recorded in this report.
- b. AC power line Conducted Emission was tested under maximum output power.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 8 of 70 Report Issued Date: Sep. 17, 2014

Report No.: FR473002A

: Rev. 01 Report Version

2.2 Test Mode

The following summary table is showing all test modes to demonstrate in compliance with the standard.

| | Summary table of Test Cases | | | | | | |
|-----------------|--|---------------------------|---------------------------|--|--|--|--|
| | Data Rate / Modulation | | | | | | |
| Test Item | Bluetooth BR 1Mbps | Bluetooth EDR 2Mbps | Bluetooth EDR 3Mbps | | | | |
| | GFSK | π/4-DQPSK | 8-DPSK | | | | |
| Conducted | Mode 1: CH00_2402 MHz | Mode 4: CH00_2402 MHz | Mode 7: CH00_2402 MHz | | | | |
| Test Cases | Mode 2: CH39_2441 MHz | Mode 5: CH39_2441 MHz | Mode 8: CH39_2441 MHz | | | | |
| rest Cases | Mode 3: CH78_2480 MHz | Mode 6: CH78_2480 MHz | Mode 9: CH78_2480 MHz | | | | |
| | | Bluetooth BR 1Mbps GFS | SK . | | | | |
| Radiated | | Mode 1: CH00_2402 MHz | | | | | |
| Test Cases | Mode 2: CH39_2441 MHz | | | | | | |
| | | | | | | | |
| | | Mode 3: CH78_2480 MHz | : | | | | |
| AC | Mada 4 (OOMOSO Jalla) | | | | | | |
| AC Conducted | Mode 1:GSM850 Idle + (Charging from Ad | Bluetooth Link + WLAN Lir | nk + Earphone + USB Cable | | | | |


Remark:

- 1. For radiated test cases, the worst mode data rate 1Mbps was reported only, because this data rate has the highest RF output power at preliminary tests, and no other significantly frequencies found in conducted spurious emission.
- 2. For Radiated Test Cases, The tests were performance with Adapter, Earphone, and USB Cable .


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 9 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

2.3 Connection Diagram of Test System

<Bluetooth Tx Mode>



<AC Conducted Emission Mode>



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 10 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

2.4 Support Unit used in test configuration and system

| Item | Equipment | Trade Name | Model Name | FCC ID | Data Cable | Power Cord |
|------|--------------------|-------------|-------------------|-------------|------------|-------------------|
| 1. | System Simulator | R&S | CBT | N/A | N/A | Unshielded,1.8m |
| 2. | System Simulator | R&S | CMU 200 | N/A | N/A | Unshielded, 1.8 m |
| 3. | Bluetooth Earphone | Lenovo | LBH505 | N/A | N/A | N/A |
| 4. | WLAN AP | D-Link | DIR-855 | KA2DIR855A2 | N/A | Unshielded,1.8m |
| | | | | | | AC I/P: |
| 5. | Notebook | Lenovo G480 | G480 | FCC DoC | N/A | Unshielded, 1.2 m |
| J. | | | G 4 00 | | | DC O/P: |
| | | | | | | Shielded,1.8 m |

2.5 EUT Operation Test Setup

For Bluetooth function, the engineering test program was provided and enabled to make EUT connect with Bluetooth base station to continuous transmit/receive.

For AC power line conducted emissions, the EUT was set to connect with the WLAN AP under large package sizes transmission.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 11 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

2.6 Measurement Results Explanation Example

For all conducted test items:

The offset level is set in the spectrum analyzer to compensate the RF cable loss and attenuator factor between EUT conducted output port and spectrum analyzer. With the offset compensation, the spectrum analyzer reading level is exactly the EUT RF output level.

Example:

The spectrum analyzer offset is derived from RF cable loss and attenuator factor.

Offset = RF cable loss + attenuator factor.

Following shows an offset computation example with cable loss 6.0 dB and 10dB attenuator.

$$Offset(dB) = RF \ cable \ loss(dB) + attenuator \ factor(dB).$$

= 6.0 + 10 = 16.0 (dB)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 12 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

3 **Test Result**

3.1 Number of Channel Measurement

3.1.1 Limits of Number of Hopping Frequency

Frequency hopping systems in the 2400-2483.5 MHz band shall use at least 15 channels.

3.1.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.1.3 Test Procedure

- 1. The testing follows FCC Public Notice DA 00-705 Measurement Guidelines.
- 2. The RF output of EUT was connected to the spectrum analyzer by RF cable and attenuator. The path loss was compensated to the results for each measurement.
- 3. Set to the maximum power setting and enable the EUT transmit continuously.
- 4. Enable the EUT hopping function.
- 5. Use the following spectrum analyzer settings: Span = the frequency band of operation; RBW ≥ 1% of the span; VBW ≥ RBW; Sweep = auto; Detector function = peak; Trace = max hold.
- 6. The number of hopping frequency used is defined as the number of total channel.
- 7. Record the measurement data derived from spectrum analyzer.

3.1.4 Test Setup



3.1.5 Test Result of Number of Hopping Frequency

| Test Mode : | 1Mbps | Temperature : | 24~25 ℃ |
|-----------------|----------|---------------------|----------------|
| Test Engineer : | Fly Chen | Relative Humidity : | 49~51% |


| Number of Hopping | Adaptive Frequency | Limits | Pass/Fail | |
|-------------------|--------------------|-----------|-----------|--|
| (Channel) | Hopping (Channel) | (Channel) | | |
| 79 | 20 | > 15 | Pass | |

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 13 of 70 Report Issued Date: Sep. 17, 2014 Report Version

: Rev. 01

Number of Hopping Channel Plot on Channel 00 - 78



Date: 6.AUG.2014 14:10:20



Date: 6.AUG.2014 14:15:49

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 14 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

3.2 Hopping Channel Separation Measurement

3.2.1 Limit of Hopping Channel Separation

Frequency hopping systems operating in the 2400-2483.5 MHz band may have hopping channel carrier frequencies that are separated by 25 kHz or two-thirds of the 20 dB bandwidth of the hopping channel, whichever is greater.

3.2.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.2.3 Test Procedures

- 1. The testing follows FCC Public Notice DA 00-705 Measurement Guidelines.
- 2. The RF output of EUT was connected to the spectrum analyzer by RF cable and attenuator. The path loss was compensated to the results for each measurement.
- 3. Set to the maximum power setting and enable the EUT transmit continuously.
- 4. Enable the EUT hopping function.
- Use the following spectrum analyzer settings:
 Span = wide enough to capture the peaks of two adjacent channels; RBW ≥ 1% of the span;
 VBW ≥ RBW; Sweep = auto; Detector function = peak; Trace = max hold.
- 6. Measure and record the results in the test report.

3.2.4 Test Setup



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 15 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

3.2.5 Test Result of Hopping Channel Separation

| Test Mode : | 1Mbps | Temperature : | 24~25 ℃ |
|-----------------|----------|---------------------|----------------|
| Test Engineer : | Fly Chen | Relative Humidity : | 49~51% |

| Channel | Frequency (MHz) | Frequency Separation (MHz) | (2/3 of 20dB BW) Limits (MHz) | Pass/Fail |
|---------|--------------------|----------------------------|----------------------------------|-----------|
| 00 | 2402 | 1.002 | 0.6267 | Pass |
| 39 | 2441 | 1.002 | 0.6240 | Pass |
| 78 | 2480 | 1.002 | 0.5947 | Pass |


Channel Separation Plot on Channel 00 - 01



Date: 6.AUG.2014 13:29:13


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 16 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

Channel Separation Plot on Channel 39 - 40



Date: 6.AUG.2014 13:29:54

Channel Separation Plot on Channel 77 - 78




Date: 6.AUG.2014 13:30:35

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 17 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

| Test Mode : | 2Mbps | Temperature : | 24~25℃ |
|-----------------|----------|---------------------|--------|
| Test Engineer : | Fly Chen | Relative Humidity : | 49~51% |

| Channel | Frequency (MHz) | Frequency Separation (MHz) | (2/3 of 20dB BW) Limits (MHz) | Pass/Fail |
|---------|--------------------|----------------------------|----------------------------------|-----------|
| 00 | 2402 | 1.002 | 0.8440 | Pass |
| 39 | 2441 | 1.008 | 0.8400 | Pass |
| 78 | 2480 | 1.008 | 0.8320 | Pass |


Channel Separation Plot on Channel 00 - 01



Date: 6.AUG.2014 13:35:28


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 18 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

Channel Separation Plot on Channel 39 - 40



Date: 6.AUG.2014 13:36:13

Channel Separation Plot on Channel 77 - 78



Date: 6.AUG.2014 13:37:09

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 19 of 70 Report Issued Date: Sep. 17, 2014


Report No.: FR473002A

: Rev. 01 Report Version

| Test Mode : | 3Mbps | Temperature : | 24~25 ℃ |
|-----------------|----------|---------------------|----------------|
| Test Engineer : | Fly Chen | Relative Humidity : | 49~51% |

| Channel | Frequency (MHz) | Frequency Separation (MHz) | (2/3 of 20dB BW) Limits (MHz) | Pass/Fail |
|---------|--------------------|----------------------------|----------------------------------|-----------|
| 00 | 2402 | 1.002 | 0.8320 | Pass |
| 39 | 2441 | 1.002 | 0.8240 | Pass |
| 78 | 2480 | 1.002 | 0.8320 | Pass |


Channel Separation Plot on Channel 00 - 01



Date: 6.AUG.2014 13:37:51


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 20 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

Channel Separation Plot on Channel 39 - 40



Date: 6.AUG.2014 13:43:06

Channel Separation Plot on Channel 77 - 78



Date: 6.AUG.2014 13:43:46

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 21 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

3.3 Dwell Time Measurement

3.3.1 Limit of Dwell Time

The average time of occupancy on any channel shall not be greater than 0.4 seconds within a period of 0.4 seconds multiplied by the number of hopping channels employed.

3.3.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.3.3 Test Procedures

- 1. The testing follows FCC Public Notice DA 00-705 Measurement Guidelines.
- The RF output of EUT was connected to the spectrum analyzer by RF cable and attenuator.
 The path loss was compensated to the results for each measurement.
- 3. Set to the maximum power setting and enable the EUT transmit continuously.
- 4. Enable the EUT hopping function.
- 5. Use the following spectrum analyzer settings: Span = zero span, centered on a hopping channel; RBW = 1 MHz; VBW ≥ RBW; Sweep = as necessary to capture the entire dwell time per hopping channel; Detector function = peak; Trace = max hold.
- 6. Measure and record the results in the test report.

3.3.4 Test Setup



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 22 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

3.3.5 Test Result of Dwell Time

| Test Mode : | DH5 | Temperature : | 24~25 ℃ |
|-----------------|----------|---------------------|----------------|
| Test Engineer : | Fly Chen | Relative Humidity : | 49~51% |

| Mode | Channel | Hops Over Occupancy Time(hops) | | Dwell Time (sec) | Limits (sec) | Pass/Fail |
|--------|---------|--------------------------------------|-------|---------------------|-----------------|-----------|
| Normal | 79 | 106.67 | 2.884 | 0.31 | 0.4 | Pass |
| AFH | 20 | 53.33 | 2.884 | 0.15 | 0.4 | Pass |


Remark:

- In normal mode, hopping rate is 1600 hops/s with 6 slots in 79 hopping channels.
 With channel hopping rate (1600 / 6 / 79) in Occupancy Time Limit (0.4 x 79) (s),
 Hops Over Occupancy Time comes to (1600 / 6 / 79) x (0.4 x 79) = 106.67 hops.
- 2. In AFH mode, hopping rate is 800 hops/s with 6 slots in 20 hopping channels. With channel hopping rate (800 / 6 / 20) in Occupancy Time Limit (0.4×20) (s), Hops Over Occupancy Time comes to $(800 / 6 / 20) \times (0.4 \times 20) = 53.33$ hops.
- 3. Dwell Time(s) = Hops Over Occupancy Time (hops) x Package Transfer Time

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 23 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

Package Transfer Time Plot



Date: 3.AUG.2014 23:51:31

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 24 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

3.4 20dB Bandwidth Measurement

3.4.1 Limit of 20dB Bandwidth

Reporting only

3.4.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.4.3 Test Procedures

- 1. The testing follows FCC Public Notice DA 00-705 Measurement Guidelines.
- 2. The RF output of EUT was connected to the spectrum analyzer by RF cable and attenuator. The path loss was compensated to the results for each measurement.
- 3. Set to the maximum power setting and enable the EUT transmit continuously.
- 4. Use the following spectrum analyzer settings for 20dB Bandwidth measurement. Span = approximately 2 to 3 times the 20 dB bandwidth, centered on a hopping channel; RBW ≥ 1% of the 20 dB bandwidth; VBW ≥ RBW; Sweep = auto; Detector function = peak; Trace = max hold.
- 5. Measure and record the results in the test report.

3.4.4 Test Setup



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 25 of 70 Report Issued Date: Sep. 17, 2014 : Rev. 01

Report No.: FR473002A

Report Version

3.4.5 Test Result of 20dB Bandwidth

| Test Mode : | 1Mbps | Temperature : | 24~25 ℃ |
|-----------------|----------|---------------------|----------------|
| Test Engineer : | Fly Chen | Relative Humidity : | 49~51% |


| Channel | Frequency (MHz) | 20dB Bandwidth (MHz) |
|---------|-----------------|----------------------|
| 00 | 2402 | 0.940 |
| 39 | 2441 | 0.936 |
| 78 | 2480 | 0.892 |

20 dB Bandwidth Plot on Channel 00




Date: 6.AUG.2014 13:44:21

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 26 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01



Date: 6.AUG.2014 13:44:55

20 dB Bandwidth Plot on Channel 78



Date: 6.AUG.2014 13:45:16


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 27 of 70 Report Issued Date: Sep. 17, 2014

Report No.: FR473002A

Report Version : Rev. 01


| Test Mode : | 2Mbps | Temperature : | 24~25℃ |
|-----------------|----------|---------------------|--------|
| Test Engineer : | Fly Chen | Relative Humidity : | 49~51% |

| Channel | Frequency (MHz) | 20dB Bandwidth (MHz) |
|---------|-----------------|----------------------|
| 00 | 2402 | 1.266 |
| 39 | 2441 | 1.260 |
| 78 | 2480 | 1.248 |



Date: 6.AUG.2014 13:45:40

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 28 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01



Date: 6.AUG.2014 13:46:03

20 dB Bandwidth Plot on Channel 78




Date: 6.AUG.2014 13:46:22

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 29 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01


| Test Mode : | 3Mbps | Temperature : | 24~25℃ |
|-----------------|----------|---------------------|--------|
| Test Engineer : | Fly Chen | Relative Humidity : | 49~51% |

| Channel | Frequency (MHz) | 20dB Bandwidth (MHz) |
|---------|-----------------|----------------------|
| 00 | 2402 | 1.248 |
| 39 | 2441 | 1.236 |
| 78 | 2480 | 1.248 |



Date: 6.AUG.2014 13:46:49

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 30 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01



Date: 6.AUG.2014 13:49:29

20 dB Bandwidth Plot on Channel 78



Date: 6.AUG.2014 13:50:07

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 31 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

3.5 Peak Output Power Measurement

3.5.1 Limit of Peak Output Power

Section 15.247 (b) The maximum peak conducted output power of the intentional radiator shall not exceed the following: (1) For frequency hopping systems operating in the 2400-2483.5 MHz band employing at least 75 non-overlapping hopping channels, and all frequency hopping systems in the 5725-5850 MHz band: 1 watt. For all other frequency hopping systems in the 2400-2483.5 MHz band 0.125 watts.

3.5.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.5.3 Test Procedures

- 1. The testing follows FCC Public Notice DA 00-705 Measurement Guidelines.
- 2. The RF output of EUT was connected to the power meter by RF cable and attenuator. The path loss was compensated to the results for each measurement.
- 3. Set to the maximum power setting and enable the EUT transmit continuously.
- 4. Measure the conducted output power with cable loss and record the results in the test report.
- 5. Measure and record the results in the test report.

3.5.4 Test Setup



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 32 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

3.5.5 Test Result of Peak Output Power

| Test Mode : | 1Mbps | Temperature : | 24~25 ℃ |
|-----------------|----------|---------------------|----------------|
| Test Engineer : | Fly Chen | Relative Humidity : | 49~51% |

| Francis | | RF Power (dBm) | | | |
|---------|-----------|-------------------------------|-------|-----------|--|
| Channel | Frequency | GFSK Max. Limits 1 Mbps (dBm) | | Dece/Feil | |
| | (MHz) | | | Pass/Fail | |
| 00 | 2402 | 3.45 | 20.97 | Pass | |
| 39 | 2441 | 5.22 | 20.97 | Pass | |
| 78 | 2480 | 5.42 | 20.97 | Pass | |

| Test Mode : | 2Mbps | Temperature : | 24~25℃ |
|-----------------|----------|---------------------|--------|
| Test Engineer : | Fly Chen | Relative Humidity : | 49~51% |

| Francis | | RF Power (dBm) | | |
|---------|-----------|----------------|-------------|-----------|
| Channel | Frequency | π/4-DQPSK | Max. Limits | Pass/Fail |
| | (MHz) | 2 Mbps | | |
| 00 | 2402 | 3.18 | 20.97 | Pass |
| 39 | 2441 | 4.89 | 20.97 | Pass |
| 78 | 2480 | 5.09 | 20.97 | Pass |

| Test Mode: | 3Mbps | Temperature : | 24~25 ℃ |
|-----------------|----------|---------------------|----------------|
| Test Engineer : | Fly Chen | Relative Humidity : | 49~51% |

| | Eroguenev | RF Power (dBm) | | | |
|---------|-----------|----------------|-------------|-----------|--|
| Channel | Frequency | 8-DPSK | Max. Limits | Pass/Fail | |
| | (MHz) | 3 Mbps (dBm) | | Pass/Fall | |
| 00 | 2402 | 3.21 | 20.97 | Pass | |
| 39 | 2441 | 4.91 | 20.97 | Pass | |
| 78 | 2480 | 5.06 | 20.97 | Pass | |

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 33 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

3.6 Conducted Band Edges Measurement

3.6.1 Limit of Band Edges

In any 100 kHz bandwidth outside the intentional radiation frequency band, the radio frequency power shall be at least 20 dB below the highest level of the radiated power. In addition, radiated emissions which fall in the restricted bands must also comply with the radiated emission limits.

3.6.2 **Measuring Instruments**

The measuring equipment is listed in the section 4 of this test report.

3.6.3 **Test Procedures**

- The testing follows the guidelines in Band-edge Compliance of RF Conducted Emissions of FCC Public Notice DA 00-705 Measurement Guidelines.
- 2. Set to the maximum power setting and enable the EUT transmit continuously.
- 3. Set RBW = 100kHz (≥ 1% span=10MHz), VBW = 300kHz (≥ RBW). Band edge emissions must be at least 20 dB down from the highest emission level within the authorized band as measured with a 100kHz RBW. The attenuation shall be 30 dB instead of 20 dB when RMS conducted output power procedure is used.
- 4. Enable hopping function of the EUT and then repeat step 2. and 3.
- 5. Measure and record the results in the test report.

3.6.4 Test Setup



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 34 of 70 Report Issued Date: Sep. 17, 2014


Report No.: FR473002A

Report Version : Rev. 01

3.6.5 Test Result of Conducted Band Edges


| Test Mode : | 1Mbps | Temperature : | 24~25 ℃ |
|----------------|-----------|---------------------|----------------|
| Test Channel : | 00 and 78 | Relative Humidity : | 49~51% |
| | | Test Engineer : | Fly Chen |

Low Band Edge Plot on Channel 00



Date: 6.AUG.2014 13:51:01

High Band Edge Plot on Channel 78




Date: 6.AUG.2014 13:51:53

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 35 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01


| Test Mode : | 2Mbps | Temperature : | 24~25 ℃ |
|----------------|-----------|---------------------|----------------|
| Test Channel : | 00 and 78 | Relative Humidity : | 49~51% |
| | | Test Engineer : | Fly Chen |

Low Band Edge Plot on Channel 00



Date: 6.AUG.2014 13:52:45

High Band Edge Plot on Channel 78




Date: 6.AUG.2014 13:53:36

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 36 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01


| Test Mode : | 3Mbps | Temperature : | 24~25 ℃ |
|----------------|-----------|---------------------|----------------|
| Test Channel : | 00 and 78 | Relative Humidity : | 49~51% |
| | | Test Engineer : | Fly Chen |

Low Band Edge Plot on Channel 00



Date: 6.AUG.2014 13:54:28

High Band Edge Plot on Channel 78




Date: 6.AUG.2014 13:55:19

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 37 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

3.6.6 Test Result of Conducted Hopping Mode Band Edges


| Test Mode: | 1Mbps | Temperature : | 24~25 ℃ |
|-----------------|----------|---------------------|----------------|
| Test Engineer : | Fly Chen | Relative Humidity : | 49~51% |

1Mbps Hopping Mode Low Band Edge Plot



Date: 6.AUG.2014 14:24:49

1Mbps Hopping Mode High Band Edge Plot




Date: 6.AUG.2014 14:26:17

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 38 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01


| Test Mode : | 2Mbps | Temperature : | 24~25 ℃ |
|-----------------|----------|---------------------|----------------|
| Test Engineer : | Fly Chen | Relative Humidity : | 49~51% |

2Mbps Hopping Mode Low Band Edge Plot



Date: 6.AUG.2014 14:29:28

2Mbps Hopping Mode High Band Edge Plot




Date: 6.AUG.2014 14:27:43

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 39 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01


| Test Mode : | 3Mbps | Temperature : | 24~25 ℃ |
|-----------------|----------|---------------------|----------------|
| Test Engineer : | Fly Chen | Relative Humidity : | 49~51% |

3Mbps Hopping Mode Low Band Edge Plot



Date: 6.AUG.2014 14:31:03

3Mbps Hopping Mode High Band Edge Plot



Date: 6.AUG.2014 14:32:03

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 40 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

3.7 Conducted Spurious Emission Measurement

Limit of Spurious Emission Measurement

In any 100 kHz bandwidth outside the intentional radiation frequency band, the radio frequency power shall be at least 20 dB below the highest level of the radiated power. In addition, radiated emissions which fall in the restricted bands must also comply with the radiated emission limits.

3.7.2 **Measuring Instruments**

The measuring equipment is listed in the section 4 of this test report.

3.7.3 Test Procedure

- 1. The testing follows the guidelines in Spurious RF Conducted Emissions of FCC Public Notice DA 00-705 Measurement Guidelines
- 2. The RF output of EUT was connected to the spectrum analyzer by RF cable and attenuator. The path loss was compensated to the results for each measurement.
- 3. Set to the maximum power setting and enable the EUT transmit continuously.
- 4. Set RBW = 100 kHz, VBW = 300kHz, scan up through 10th harmonic. All harmonics / spurs must be at least 20 dB down from the highest emission level within the authorized band as measured with a 100 kHz RBW.
- 5. Measure and record the results in the test report.
- 6. The RF fundamental frequency should be excluded against the limit line in the operating frequency band.

3.7.4 Test Setup



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 41 of 70 Report Issued Date: Sep. 17, 2014 Report Version


Report No.: FR473002A

: Rev. 01

3.7.5 Test Result of Conducted Spurious Emission


| Test Mode : | 1Mbps | Temperature : | 24~25℃ |
|----------------|-------|---------------------|----------|
| Test Channel : | 00 | Relative Humidity : | 49~51% |
| | | Test Engineer : | Fly Chen |

1Mbps CSE Plot on Ch 00 between 30MHz ~ 3 GHz



Date: 6.AUG.2014 15:06:27

1Mbps CSE Plot on Ch 00 between 2 GHz ~ 25 GHz



Date: 6.AUG.2014 15:07:18

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 42 of 70
Report Issued Date : Sep. 17, 2014

Report No.: FR473002A

Report Version : Rev. 01


| Test Mode : | 1Mbps | Temperature : | 24~25℃ |
|----------------|-------|---------------------|----------|
| Test Channel : | 39 | Relative Humidity : | 49~51% |
| | | Test Engineer : | Fly Chen |

1Mbps CSE Plot on Ch 39 between 30MHz ~ 3 GHz



Date: 6.AUG.2014 15:08:11

1Mbps CSE Plot on Ch 39 between 2 GHz ~ 25 GHz




Date: 6.AUG.2014 15:09:02

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 43 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01


| Test Mode : | 1Mbps | Temperature : | 24~25℃ |
|----------------|-------|---------------------|----------|
| Test Channel : | 78 | Relative Humidity : | 49~51% |
| | | Test Engineer : | Fly Chen |

1Mbps CSE Plot on Ch 78 between 30MHz ~ 3 GHz



Date: 6.AUG.2014 15:09:55

1Mbps CSE Plot on Ch 78 between 2 GHz ~ 25 GHz




Date: 6.AUG.2014 15:10:47

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 44 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01


| Test Mode : | 2Mbps | Temperature : | 24~25℃ |
|----------------|-------|---------------------|----------|
| Test Channel : | 00 | Relative Humidity : | 49~51% |
| | | Test Engineer : | Fly Chen |

2Mbps CSE Plot on Ch 00 between 30MHz ~ 3 GHz



Date: 6.AUG.2014 14:43:10

2Mbps CSE Plot on Ch 00 between 2 GHz ~ 25 GHz




Date: 6.AUG.2014 14:44:01

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 45 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01


| Test Mode : | 2Mbps | Temperature : | 24~25℃ |
|----------------|-------|---------------------|----------|
| Test Channel : | 39 | Relative Humidity : | 49~51% |
| | | Test Engineer : | Fly Chen |

2Mbps CSE Plot on Ch 39 between 30MHz ~ 3 GHz



Date: 6.AUG.2014 14:44:54

2Mbps CSE Plot on Ch 39 between 2 GHz ~ 25 GHz




Date: 6.AUG.2014 14:45:46

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 46 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01


| Test Mode : | 2Mbps | Temperature : | 24~25℃ |
|----------------|-------|---------------------|----------|
| Test Channel : | 78 | Relative Humidity : | 49~51% |
| | | Test Engineer : | Fly Chen |

2Mbps CSE Plot on Ch 78 between 30MHz ~ 3 GHz



Date: 6.AUG.2014 14:46:38

2Mbps CSE Plot on Ch 78 between 2 GHz ~ 25 GHz




Date: 6.AUG.2014 14:47:29

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 47 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01


| Test Mode : | 3Mbps | Temperature : | 24~25 ℃ |
|----------------|-------|---------------------|----------------|
| Test Channel : | 00 | Relative Humidity : | 49~51% |
| | | Test Engineer : | Fly Chen |

3Mbps CSE Plot on Ch 00 between 30MHz ~ 3 GHz



Date: 6.AUG.2014 14:48:54

3Mbps CSE Plot on Ch 00 between 2 GHz ~ 25 GHz




Date: 6.AUG.2014 14:49:46

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 48 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01


| Test Mode : | 3Mbps | Temperature : | 24~25℃ |
|----------------|-------|---------------------|----------|
| Test Channel : | 39 | Relative Humidity : | 49~51% |
| | | Test Engineer : | Fly Chen |

3Mbps CSE Plot on Ch 39 between 30MHz ~ 3 GHz



Date: 6.AUG.2014 14:50:38

3Mbps CSE Plot on Ch 39 between 2 GHz ~ 25 GHz




Date: 6.AUG.2014 14:51:30

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 49 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01




| Test Mode : | 3Mbps | Temperature : | 24~25℃ |
|----------------|-------|---------------------|----------|
| Test Channel : | 78 | Relative Humidity : | 49~51% |
| | | Test Engineer : | Fly Chen |

3Mbps CSE Plot on Ch 78 between 30MHz ~ 3 GHz



Date: 6.AUG.2014 14:52:22

3Mbps CSE Plot on Ch 78 between 2 GHz ~ 25 GHz



Date: 6.AUG.2014 14:53:14

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 50 of 70 Report Issued Date: Sep. 17, 2014 Report Version : Rev. 01

3.8 Radiated Band Edges and Spurious Emission Measurement

3.8.1 Limit of Radiated Band Edges and Spurious Emission

In any 100 kHz bandwidth outside the intentional radiator frequency band, all harmonics/spurious must be at least 20 dB below the highest emission level within the authorized band. In addition, radiated emissions which fall in the restricted bands must also comply with the FCC section 15.209 limits as below.

| Frequency | Field Strength | Measurement Distance |
|---------------|--------------------|----------------------|
| (MHz) | (microvolts/meter) | (meters) |
| 0.009 - 0.490 | 2400/F(kHz) | 300 |
| 0.490 – 1.705 | 24000/F(kHz) | 30 |
| 1.705 – 30.0 | 30 | 30 |
| 30 – 88 | 100 | 3 |
| 88 – 216 | 150 | 3 |
| 216 - 960 | 200 | 3 |
| Above 960 | 500 | 3 |

3.8.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 51 of 70
Report Issued Date : Sep. 17, 2014

Report No.: FR473002A

Report Version : Rev. 01

3.8.3 Test Procedures

 The testing follows the guidelines in Spurious Radiated Emissions of FCC Public Notice DA 00-705 Measurement Guidelines.

Report No.: FR473002A

: 52 of 70

: Rev. 01

Report Issued Date: Sep. 17, 2014

Page Number

Report Version

- 2. The EUT was placed on a turntable with 0.8 meter above ground.
- 3. The EUT was set 3 meters from the interference receiving antenna, which was mounted on the top of a variable height antenna tower.
- 4. For each suspected emission, the EUT was arranged to its worst case and then tune the Antenna tower (from 1 m to 4 m) and turntable (from 0 degree to 360 degrees) to find the maximum reading. A pre-amp and a high pass filter are used for the test in order to get better signal level to comply with the guidelines.
- 5. Set to the maximum power setting and enable the EUT transmit continuously.
- 6. Use the following spectrum analyzer settings:
 - (1) Span shall wide enough to fully capture the emission being measured;
 - (2) Set RBW=100 kHz for f < 1 GHz, RBW=1MHz for f>1GHz; VBW ≥ RBW; Sweep = auto; Detector function = peak; Trace = max hold for peak
 - (3) For average measurement: use duty cycle correction factor method per 15.35(c). Duty cycle = On time/100 milliseconds

 On time = $N_1*L_1+N_2*L_2+...+N_{n-1}*LN_{n-1}+N_n*L_n$ Where N_1 is number of type 1 pulses, L_1 is length of type 1 pulses, etc.

 Average Emission Level = Peak Emission Level + 20*log(Duty cycle)
- 7. Corrected Reading: Antenna Factor + Cable Loss + Read Level Preamp Factor = Level

Note: The average levels were calculated from the peak level corrected with duty cycle correction factor (-24.79dB) derived from 20log (dwell time/100ms). This correction is only for signals that hop with the fundamental signal, such as band-edge and harmonic. Other spurious signals that are independent of the hopping signal would not use this correction.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45

3.8.4 Test Setup

For radiated emissions below 30MHz




For radiated emissions from 30MHz to 1GHz



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 53 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

For radiated emissions above 1GHz




3.8.5 Test Results of Radiated Spurious Emissions (9 kHz ~ 30 MHz)

The low frequency, which started from 9 kHz to 30MHz, was pre-scanned and the result which was 20dB lower than the limit line per 15.31(o) was not reported.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 54 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

3.8.6 Duty cycle correction factor for average measurement

DH5 on time (One Pulse) Plot on Channel 39



DH5 on time (Count Pulses) Plot on Channel 39



Note:

- 1. Worst case Duty cycle = on time/100 milliseconds = $2 \times 2.88 / 100 = 5.76 \%$
- 2. Worst case Duty cycle correction factor = 20*log(Duty cycle) = -24.79 dB
- 3. DH5 has the highest duty cycle worst case and is reported.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 55 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

Duty Cycle Correction Factor Consideration for AFH mode:

Bluetooth normal hopping rate is 1600Hz and reduced to 800Hz in AFH mode; due to the reduced number of hopping frequencies, with the same packet configuration the dwell time in each channel frequency within 100msec period is longer in AFH mode than normal mode.

In AFH mode, the minimum hopping frequencies are 20, to get the longest dwell time DH5 packet is observed; the period to have DH5 packet completing one hopping sequence is

2.88 ms x 20 channels = 57.6 ms

There cannot be 2 complete hopping sequences within 100ms period, considering the random hopping behavior, maximum 2 hops can be possibly observed within the period. [100ms / 57.6ms] = 2 hops

Thus, the maximum possible ON time:

2.88 ms x 2 = 5.76 ms

Worst case Duty Cycle Correction factor, which is derived from the maximum possible ON time,

 $20 \times log(5.76 \text{ ms}/100\text{ms}) = -24.79 \text{ dB}$

Page Number : 56 of 70 Report Issued Date : Sep. 17, 2014

Report No.: FR473002A

Report Version : Rev. 01

3.8.7 Test Result of Radiated Spurious at Band Edges

| Test Mode : | 1Mbps | Temperature : | 22~23°C |
|----------------|-------|---------------------|----------|
| Test Channel : | 00 | Relative Humidity : | 42~43% |
| | | Test Engineer : | Simon Lu |

| | ANTENNA POLARITY : HORIZONTAL | | | | | | | | | | | | |
|-----------|-------------------------------|--|------------|--------|--------|--------|--------|--------|-------|---------|--|--|--|
| Frequency | Level | Level Over Limit Read Antenna Cable Preamp Ant Tab | | | | | | | Table | Remark | | | |
| | | Limit | Line | Level | Factor | Loss | Factor | Pos | Pos | | | | |
| (MHz) | (dBµV/m) | (dB) | (dBµV/m) | (dBµV) | (dB) | (dB) | (dB) | (cm) | (deg) | | | | |
| 2365.53 | 46.52 | -27.48 | 74 | 48.26 | 31.89 | 2.62 | 36.25 | 100 | 48 | Peak | | | |
| 2365.53 | 21.73 | -32.27 | 54 | - | - | - | - | - | - | Average | | | |

| | ANTENNA POLARITY : VERTICAL | | | | | | | | | | | |
|-----------|-----------------------------|--------|------------|--------|---------|--------|--------|--------|-------|---------|--|--|
| Frequency | Level | Over | Limit | Read | Antenna | Cable | Preamp | Ant | Table | Remark | | |
| | | Limit | Line | Level | Factor | Loss | Factor | Pos | Pos | | | |
| (MHz) | (dBµV/m) | (dB) | (dBµV/m) | (dBµV) | (dB) | (dB) | (dB) | (cm) | (deg) | | | |
| 2389.56 | 47.09 | -26.91 | 74 | 48.52 | 32.01 | 2.64 | 36.08 | 105 | 30 | Peak | | |
| 2389.56 | 22.30 | -31.70 | 54 | - | - | - | - | - | - | Average | | |

| Test Mode : | 1Mbps | Temperature : | 22~23°C |
|----------------|-------|---------------------|----------|
| Test Channel : | 78 | Relative Humidity : | 42~43% |
| | | Test Engineer : | Simon Lu |

| | ANTENNA POLARITY : HORIZONTAL | | | | | | | | | | | |
|-----------|-------------------------------|--------|------------|--------|---------|--------|--------|--------|---------|---------|--|--|
| Frequency | Level | Over | Limit | Read | Antenna | Cable | Preamp | Ant | Table | Remark | | |
| | | Limit | Line | Level | Factor | Loss | Factor | Pos | Pos | | | |
| (MHz) | (dBµV/m) | (dB) | (dBµV/m) | (dBµV) | (dB) | (dB) | (dB) | (cm) | (deg) | | | |
| 2483.53 | 50.89 | -23.11 | 74 | 51.66 | 32.34 | 2.68 | 35.79 | 100 | 44 | Peak | | |
| 2483.53 | 26.10 | -27.90 | 54 | - | - | - | - | - | - | Average | | |

| | ANTENNA POLARITY : VERTICAL | | | | | | | | | | | |
|-----------|-----------------------------|---------------|---------------|---------------|-------------------|---------------|------------------|------------|--------------|---------|--|--|
| Frequency | Level | Over Limit | Limit Line | Read Level | Antenna Factor | Cable Loss | Preamp Factor | Ant Pos | Table Pos | Remark | | |
| (MHz) | (dBµV/m) | (dB) | (dBµV/m) | (dBµV) | (dB) | (dB) | (dB) | (cm) | (deg) | | | |
| 2483.68 | 49.61 | -24.39 | 74 | 50.38 | 32.34 | 2.68 | 35.79 | 102 | 25 | Peak | | |
| 2483.68 | 24.82 | -29.18 | 54 | - | - | - | - | - | - | Average | | |

Note: Average Emission Level = Peak Emission Level + duty cycle correction factor(-24.79dB)

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 57 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

3.8.8 Test Result of Radiated Spurious Emission (30MHz ~ 10th Harmonic)

Note: Pre-scanned all test modes and only choose the worst case mode recorded in the test report for radiated spurious emission below 1GHz.

| Test Mode : | 1Mbps | Temperature : | 22~23°C | | | | |
|-----------------|--|--------------------------|------------|--|--|--|--|
| Test Channel : | 00 | Relative Humidity : | 42~43% | | | | |
| Test Engineer : | Simon Lu | Polarization : | Horizontal | | | | |
| | 1. 2402 MHz is fundamer | ntal signal which can be | e ignored. | | | | |
| Remark : | 2. Average measurement was not performed if peak level went lower than the | | | | | | |
| | average limit. | | | | | | |

| Frequency | Level | Over | Limit | Read | Antenna | Cable | Preamp | Ant | Table | Remark |
|-----------|------------|--------|------------|--------|---------|-------|--------|--------|-------|---------|
| | | Limit | Line | Level | Factor | Loss | Factor | Pos | Pos | |
| (MHz) | (dBµV/m) | (dB) | (dBµV/m) | (dBµV) | (dB) | (dB) | (dB) | (cm) | (deg) | |
| 2402 | 102.53 | - | - | 103.95 | 32.01 | 2.65 | 36.08 | 100 | 48 | Peak |
| 2402 | 77.74 | - | - | - | - | - | - | 100 | 48 | Average |
| 4804 | 45.42 | -28.58 | 74 | 44.03 | 34.2 | 3.78 | 36.59 | 107 | 14 | Peak |

Note: 1. Other harmonics are lower than background noise.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 58 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

^{2.} Average Emission Level = Peak Emission Level + duty cycle correction factor(-24.79)

| Test Mode : | 1Mbps | Temperature : | 22~23°C | | | | | |
|-----------------|--|--|----------|--|--|--|--|--|
| Test Channel : | 00 | Relative Humidity : | 42~43% | | | | | |
| Test Engineer : | Simon Lu | Polarization : | Vertical | | | | | |
| | 1. 2402 MHz is fundamenta | 2402 MHz is fundamental signal which can be ignored. | | | | | | |
| Remark : | 2. Average measurement was not performed if peak level went lower than the | | | | | | | |
| | average limit. | | | | | | | |

| Frequency | Level | Over | Limit | Read | Antenna | Cable | Preamp | Ant | Table | Remark |
|-----------|---------------|--------|-----------------|--------|---------|--------|--------|--------|-------|---------|
| | | Limit | Line | Level | Factor | Loss | Factor | Pos | Pos | |
| (MHz) | $(dB\mu V/m)$ | (dB) | ($dB\mu V/m$) | (dBµV) | (dB) | (dB) | (dB) | (cm) | (deg) | |
| 2402 | 101.32 | - | - | 102.74 | 32.01 | 2.65 | 36.08 | 105 | 30 | Peak |
| 2402 | 76.53 | - | - | - | - | - | - | 105 | 30 | Average |
| 4804 | 44.67 | -29.33 | 74 | 43.28 | 34.2 | 3.78 | 36.59 | 125 | 142 | Peak |

Note: 1. Other harmonics are lower than background noise.

2. Average Emission Level = Peak Emission Level + duty cycle correction factor(-24.79)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 59 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

| Test Mode : | 1Mbps | Temperature : | 22~23°C |
|-----------------|--------------------------|------------------------|--------------------------------|
| Test Channel : | 39 | Relative Humidity : | 42~43% |
| Test Engineer : | Simon Lu | Polarization : | Horizontal |
| | 1. 2441 MHz is fundament | al signal which can be | ignored. |
| Remark : | 2. Average measurement | was not performed if | peak level went lower than the |
| | average limit. | | |

| Frequency | Level | Over Limit | Limit Line | Read Level | Antenna Factor | Cable Loss | Preamp Factor | Ant Pos | Table Pos | Remark |
|-----------|------------|---------------|---------------|---------------|-------------------|---------------|------------------|------------|--------------|---------|
| (MHz) | (dBµV/m) | (dB) | (dBµV/m) | (dBµV) | (dB) | (dB) | (dB) | (cm) | (deg) | |
| 2441 | 101.98 | - | - | 103.02 | 32.21 | 2.66 | 35.91 | 125 | 173 | Peak |
| 2441 | 77.19 | - | - | - | - | - | - | 125 | 173 | Average |
| 4882 | 44.5 | -29.5 | 74 | 43.36 | 34.2 | 3.78 | 36.84 | 100 | 78 | Peak |
| 7324 | 44.73 | -29.27 | 74 | 43.18 | 35.73 | 4.74 | 38.92 | 100 | 35 | Peak |

2. Average Emission Level = Peak Emission Level + duty cycle correction factor(-24.79)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 60 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

| Test Mode : | 1Mbps | Temperature : | 22~23°C | | |
|-----------------|---|------------------------|----------|--|--|
| Test Channel : | 39 | Relative Humidity : | 42~43% | | |
| Test Engineer : | Simon Lu | Polarization : | Vertical | | |
| | 1. 2441 MHz is fundament | al signal which can be | ignored. | | |
| Remark : | 2. Average measurement was not performed if peak level went lower than th | | | | |
| | average limit. | | | | |

| Frequency (MHz) | Level | Over Limit (dB) | Limit Line (dBµV/m) | Read Level (dBµV) | Antenna Factor (dB) | Cable Loss (dB) | Preamp Factor (dB) | Ant Pos (cm) | Table Pos (deg) | Remark |
|----------------------|--------|-------------------------|-----------------------------|-------------------------|-----------------------------|-------------------------|----------------------------|----------------------|-------------------------|---------|
| 2441 | 101.21 | - (ub) | - - | 102.25 | 32.21 | 2.66 | 35.91 | 100 | 30 | Peak |
| 2441 | 76.42 | - | - | - | - | - | - | 100 | 30 | Average |
| 4882 | 44.65 | -29.35 | 74 | 43.51 | 34.2 | 3.78 | 36.84 | 100 | 63 | Peak |
| 7324 | 45.08 | -28.92 | 74 | 43.53 | 35.73 | 4.74 | 38.92 | 110 | 164 | Peak |

2. Average Emission Level = Peak Emission Level + duty cycle correction factor(-24.79)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 61 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

| Test Mode : | 1Mbps | Temperature : | 22~23°C | | | | |
|-----------------|--|---|------------|--|--|--|--|
| Test Channel : | 78 | Relative Humidity : | 42~43% | | | | |
| Test Engineer : | Simon Lu | Polarization : | Horizontal | | | | |
| | 2480 MHz is fundamental signal which can be ignored. | | | | | | |
| Remark : | 2. Average measurement | . Average measurement was not performed if peak level went lower than the | | | | | |

| Frequency | Level | Over | Limit | Read | Antenna | Cable | Preamp | Ant | Table | Remark |
|-----------|------------|---------------|--------------------|-----------------|------------------|--------------|-------------|-------------|----------------|---------|
| (MHz) | (dBµV/m) | Limit (dB) | Line (dBµV/m) | Level (dBµV) | Factor (dB) | Loss (dB) | Factor (dB) | Pos (cm) | Pos (deg) | |
| 31.94 | 23.04 | -16.96 | 40 | 38.7 | 16.8 | 0.19 | 32.65 | 100 | 150 | Peak |
| 103.72 | 23.31 | -20.19 | 43.5 | 44.32 | 11.2 | 0.43 | 32.64 | - | - | Peak |
| 120.21 | 16.84 | -26.66 | 43.5 | 37 | 11.9 | 0.58 | 32.64 | - | - | Peak |
| 173.56 | 25.96 | -17.54 | 43.5 | 48.64 | 8.98 | 0.83 | 32.49 | - | - | Peak |
| 199.75 | 23.38 | -20.12 | 43.5 | 46.14 | 9 | 0.71 | 32.47 | - | - | Peak |
| 341.37 | 19.13 | -26.87 | 46 | 36.47 | 14.15 | 0.87 | 32.36 | - | - | Peak |
| 2480 | 101.5 | - | - | 102.28 | 32.34 | 2.67 | 35.79 | 100 | 44 | Peak |
| 2480 | 76.71 | - | - | - | - | - | - | 100 | 44 | Average |
| 4960 | 44.64 | -29.36 | 74 | 43.81 | 34.2 | 3.78 | 37.15 | 100 | 56 | Peak |
| 7440 | 45.53 | -28.47 | 74 | 43.86 | 35.78 | 4.8 | 38.91 | 100 | 240 | Peak |

average limit.

2. Average Emission Level = Peak Emission Level + duty cycle correction factor(-24.79)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 62 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01



| Test Mode : | 1Mbps | Temperature : | 22~23°C | | |
|-----------------|--|------------------------|----------|--|--|
| Test Channel : | 78 | Relative Humidity : | 42~43% | | |
| Test Engineer : | Simon Lu | Polarization : | Vertical | | |
| | 1. 2480 MHz is fundament | al signal which can be | ignored. | | |
| Remark : | 2. Average measurement was not performed if peak level went lower that | | | | |
| | average limit. | | | | |

| Frequency | Level | Over Limit | Limit Line | Read Level | Antenna Factor | Cable Loss | Preamp Factor | Ant Pos | Table Pos | Remark |
|-----------|------------|---------------|---------------|---------------|-------------------|---------------|------------------|------------|--------------|---------|
| (MHz) | (dBµV/m) | (dB) | (dBµV/m) | (dBµV) | (dB) | (dB) | (dB) | (cm) | (deg) | |
| 30 | 29.33 | -10.67 | 40 | 43.8 | 18 | 0.19 | 32.66 | 100 | 236 | Peak |
| 44.55 | 24.97 | -15.03 | 40 | 47.13 | 10.2 | 0.31 | 32.67 | - | - | Peak |
| 54.25 | 27.62 | -12.38 | 40 | 53.51 | 6.4 | 0.31 | 32.6 | - | - | Peak |
| 98.87 | 21.03 | -22.47 | 43.5 | 42.78 | 10.45 | 0.43 | 32.63 | - | - | Peak |
| 172.59 | 16.29 | -27.21 | 43.5 | 38.9 | 9.06 | 0.83 | 32.5 | - | - | Peak |
| 188.11 | 15.95 | -27.55 | 43.5 | 39.16 | 8.55 | 0.71 | 32.47 | - | - | Peak |
| 2480 | 99.52 | - | - | 100.3 | 32.34 | 2.67 | 35.79 | 102 | 25 | Peak |
| 2480 | 74.73 | - | - | - | - | - | - | 102 | 25 | Average |
| 4960 | 42.71 | -31.29 | 74 | 41.88 | 34.2 | 3.78 | 37.15 | 100 | 143 | Peak |
| 7440 | 48.47 | -25.53 | 74 | 46.8 | 35.78 | 4.8 | 38.91 | 114 | 250 | Peak |

2. Average Emission Level = Peak Emission Level + duty cycle correction factor(-24.79)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 63 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

3.9 AC Conducted Emission Measurement

3.9.1 Limit of AC Conducted Emission

For equipment that is designed to be connected to the public utility (AC) power line, the radio frequency voltage that is conducted back onto the AC power line on any frequency or frequencies within the band 150 kHz to 30 MHz shall not exceed the limits in the following table.

| Eroquency of emission (MUz) | Conducted | limit (dΒμV) |
|-----------------------------|------------|--------------|
| Frequency of emission (MHz) | Quasi-peak | Average |
| 0.15-0.5 | 66 to 56* | 56 to 46* |
| 0.5-5 | 56 | 46 |
| 5-30 | 60 | 50 |

^{*}Decreases with the logarithm of the frequency.

3.9.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.9.3 Test Procedures


- 1. The EUT was placed 0.4 meter from the conducting wall of the shielding room was kept at least 80 centimeters from any other grounded conducting surface.
- 2. Connect EUT to the power mains through a line impedance stabilization network (LISN).
- 3. All the support units are connecting to the other LISN.
- 4. The LISN provides 50 ohm coupling impedance for the measuring instrument.
- 5. The FCC states that a 50 ohm, 50 microhenry LISN should be used.
- 6. Both sides of AC line were checked for maximum conducted interference.
- 7. The frequency range from 150 kHz to 30 MHz was searched.
- 8. Set the test-receiver system to Peak Detect Function and specified bandwidth (IF Bandwidth = 9kHz) with Maximum Hold Mode. Then measurement is also conducted by Average Detector and Quasi-Peak Detector Function respectively.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Report No.: FR473002A

Report Version : Rev. 01




3.9.4 Test Setup



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 65 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

Test Result of AC Conducted Emission 3.9.5



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 66 of 70 Report Issued Date: Sep. 17, 2014

Report No.: FR473002A

Report Version : Rev. 01



Test Mode: **22~24**℃ Mode 1 Temperature: Test Engineer: Eligah Wang Relative Humidity: 45~47% 120Vac / 60Hz Test Voltage: Phase: Neutral GSM850 Idle + Bluetooth Link + WLAN Link + Earphone + USB Cable (Charging Function Type: from Adapter) Level (dBuV) FCC PART15C FCC PART 15C(AVG) .5 10 20 30 Frequency (MHz) : C001-KS Site Condition: FCC PART15C LISN-N20130306 NEUTRAL mode : Mode 1 Over Limit Read LISN Cable Level Factor Freq Level Limit Loss Remark dBuV dΒ MHz dBuV dB dBuV dB 33.76 -21.80 45.36 -20.20 39.53 -24.27 28.53 -25.27 23.39 -25.35 33.59 -25.15 28.18 -27.82 20.58 -25.42 27.97 -28.03 20.27 -25.73 31.33 -24.67 24.03 -21.97 10.68 Average 10.68 QP 10.59 QP 0.16 0.16 0.20 0.20 0.36 0.36 1.07 1.07 3.09 3.09 4.07 4.07 $\begin{array}{c} 55.56 \\ 65.56 \\ 63.80 \\ 53.80 \\ 48.74 \\ 58.74 \\ 56.00 \\ 46.00 \\ 56.00 \\ 56.00 \end{array}$ 21.31 32.91 27.89 16.89 12.60 22.80 17.90 10.30 17.61 9.91 20.90 13.60 1.77 1.05 1.05 0.48 0.48 0.10 0.10 0.14 0.14 1 2 3 4 5 6 7 8 9 10 10.68 Average 10.68 QP 10.59 QP 10.59 Average 10.31 QP 10.18 QP 10.18 Average 10.22 QP 10.22 Average 10.24 QP 10.24 Average 0.19 10.24 Average 46.00

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 67 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

3.10 Antenna Requirements

3.10.1 Standard Applicable

If directional gain of transmitting antennas is greater than 6dBi, the power shall be reduced by the same level in dB comparing to gain minus 6dBi. The use of a permanently attached antenna or of an antenna that uses a unique coupling to the intentional radiator shall be considered sufficient to comply with the FCC rule.

3.10.2 Antenna Anti-Replacement Construction

An embedded-in antenna design is used.

3.10.3 Antenna Gain

The antenna peak gain of EUT is less than 6 dBi. Therefore, it is not necessary to reduce maximum peak output power limit.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 68 of 70 Report Issued Date: Sep. 17, 2014

Report No.: FR473002A

Report Version : Rev. 01

4 List of Measuring Equipment

| Instrument | Manufacturer | Model No. | Serial No. | Characteristics | Calibration Date | Test Date | Due Date | Remark |
|---|--------------|-----------|------------------|----------------------------|---------------------|---------------------------------|---------------|--------------------------|
| Spectrum Analyzer | R&S | FSP40 | 100319 | 9kHz~40GHz | Dec. 28, 2013 | Aug. 03, 2014~ Aug. 06, 2014 | Dec. 27, 2014 | Conducted (TH01-KS) |
| Pulse Power Senor | Anritsu | MA2411B | 0917070 | 30MHz~40GHz | Feb. 27, 2014 | Aug. 03, 2014~ Aug. 06, 2014 | Feb. 26, 2015 | Conducted (TH01-KS) |
| Power Meter | Anritsu | ML2495A | 1005002 | 50MHz Bandwidth | Feb. 27, 2014 | Aug. 03, 2014~ Aug. 06, 2014 | Feb. 26, 2015 | Conducted (TH01-KS) |
| EMI Test Receiver | R&S | ESCI | 100534 | 9kHz~3GHz | Nov. 05, 2013 | Sep. 07, 2014 | Nov. 04, 2014 | Radiation (03CH01-KS) |
| Spectrum Analyzer | R&S | FSP30 | 101399 | 9kHz~30GHz | May 04, 2014 | Sep. 07, 2014 | May 03, 2015 | Radiation (03CH01-KS) |
| Loop Antenna | R&S | HFH2-Z2 | 100321 | 9kHz~30MHz | Oct. 09, 2013 | Sep. 07, 2014 | Oct. 08, 2014 | Radiation (03CH01-KS) |
| Bilog Antenna | SCHAFFNER | CBL6112D | 23182 | 25MHz~2GHz | Jan. 08, 2014 | Sep. 07, 2014 | Jan. 07, 2015 | Radiation (03CH01-KS) |
| Double Ridge Horn Antenna | ETS-Lindgren | 3117 | 75959 | 1GHz~18GHz | Jan. 08, 2014 | Sep. 07, 2014 | Jan. 07, 2015 | Radiation (03CH01-KS) |
| Active Horn Antenna | com-power | AHA-118 | 701030 | 1GHz~18GHz | Nov. 18, 2013 | Sep. 07, 2014 | Nov. 17, 2014 | Radiation (03CH01-KS) |
| SHF-EHF Horn | Schwarzbeck | BBHA 9170 | BBHA1702 49 | 15GHz~40GHz | Mar. 10, 2014 | Sep. 07, 2014 | Mar. 09, 2015 | Radiation (03CH01-KS) |
| Amplifier | com-power | PA-103A | 161073 | 1MHz~1GHz | May 04, 2014 | Sep. 07, 2014 | May 03, 2015 | Radiation (03CH01-KS) |
| Amplifier | Agilent | 8449B | 3008A023 71 | 1GHz~26.5GHz | Dec. 10, 2013 | Sep. 07, 2014 | Dec. 09, 2014 | Radiation (03CH01-KS) |
| AC Power Source | Chroma | 61601 | F1040900 04 | N/A | NCR | Sep. 07, 2014 | NCR | Radiation (03CH01-KS) |
| Turn Table | MF | MF7802 | N/A | 0~360 degree | NCR | Sep. 07, 2014 | NCR | Radiation (03CH01-KS) |
| Antenna Mast | MF | MF7802 | N/A | 1 m~4 m | NCR | Sep. 07, 2014 | NCR | Radiation (03CH01-KS) |
| EMI Receiver | R&S | ESCI7 | 100768 | 9kHz~7GHz; | May 04, 2014 | Aug. 14, 2014 | May 03, 2015 | Conduction (CO01-KS) |
| AC LISN | MessTec | AN3016 | 060103 | 9kHz~30MHz | Dec. 10, 2013 | Aug. 14, 2014 | Dec. 09, 2014 | Conduction (CO01-KS) |
| AC LISN (for auxiliary equipment) | MessTec | AN3016 | 060105 | 9kHz~30MHz | Dec. 10, 2013 | Aug. 14, 2014 | Dec. 09, 2014 | Conduction (CO01-KS) |
| AC Power Source | Chroma | 61602 | ABP00000 0811 | AC 0V~300V, 45Hz~1000Hz | Nov. 12, 2013 | Aug. 14, 2014 | Nov. 11, 2014 | Conduction (CO01-KS) |

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 69 of 70
Report Issued Date : Sep. 17, 2014
Report Version : Rev. 01

Uncertainty of Evaluation 5

Uncertainty of Conducted Emission Measurement (150 kHz ~ 30 MHz)

| Measuring Uncertainty for a Level of | 2.3 |
|--------------------------------------|-----|
| Confidence of 95% (U = 2Uc(y)) | 2.0 |

Uncertainty of Radiated Emission Measurement (30 MHz ~ 1000 MHz)

| Measuring Uncertainty for a Level of | 2.5 |
|--------------------------------------|-----|
| Confidence of 95% (U = 2Uc(y)) | 2.3 |

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPORT45 Page Number : 70 of 70 Report Issued Date: Sep. 17, 2014

Report No.: FR473002A

: Rev. 01 Report Version