



Appendix B. Setup Photographs

<Conducted Emission> Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDECOMN Page Number : B1 of B2
Report Issued Date : Sep. 14, 2011
Report Version : Rev. 01


Report No. : FR172805





Report No. : FR172805

<Radiated Emission>





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDECOMN Page Number : B2 of B2
Report Issued Date : Sep. 14, 2011
Report Version : Rev. 01