

Report No. : FA3D2802

Appendix D. Test Setup Photos





Right Cheek







Left Cheek

Left Tilted

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEONEM Page Number : D1 of D2
Report Issued Date : Jan. 27, 2014
Report Version : Rev. 01





Front of the DUT with Phantom 1 cm Gap



Report No.: FA3D2802

Back of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEONEM Page Number : D2 of D2 Report Issued Date: Jan. 27, 2014 Report Version : Rev. 01