3. Internal Photograph of EUT

Brand Name: BLU; Model Name: Life Play

Report No.: EP350801




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEPLAY Page Number : 11 of 27
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01

Report No.: EP350801




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEPLAY Page Number : 12 of 27
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01

Report No.: EP350801




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEPLAY Page Number : 13 of 27
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01

Report No.: EP350801




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEPLAY Page Number : 14 of 27
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01

Report No.: EP350801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEPLAY Page Number : 15 of 27
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01


Report No.: EP350801



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEPLAY Page Number : 16 of 27
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01

Report No.: EP350801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEPLAY Page Number : 17 of 27
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01


Report No.: EP350801



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEPLAY Page Number : 18 of 27
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01

Report No.: EP350801




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158
FAX: 86-0512-5790-0958
FCC ID: YHLBLULIFEPLAY


Page Number : 19 of 27
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01

Report No.: EP350801




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEPLAY Page Number : 20 of 27
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01

Report No.: EP350801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEPLAY Page Number : 21 of 27
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01


Report No.: EP350801



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEPLAY Page Number : 22 of 27
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01

Report No.: EP350801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEPLAY Page Number : 23 of 27
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01


Report No.: EP350801



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEPLAY Page Number : 24 of 27
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01


Report No.: EP350801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEPLAY Page Number : 25 of 27
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01



Report No.: EP350801




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEPLAY

: 26 of 27 Page Number Report Issued Date : Jun. 13, 2013 Report Version : Rev. 01



Report No.: EP350801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEPLAY Page Number : 27 of 27 Report Issued Date : Jun. 13, 2013 Report Version : Rev. 01