


Report No.: FR761305A

Appendix B. Setup Photographs

<Conducted Emission>





SPORTON International (ShenZhen) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUS1 Page Number : B1 of B2
Report Issued Date Jul. 12, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0






<Radiated Emission> Z Plane LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUS1 Page Number : B2 of B2
Report Issued Date Jul. 12, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR761305A