

Appendix D. Product Photos






SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUTANK45 Page Number : D1 of D2
Report Issued Date : Jan. 21, 2013
Report Version : Rev. 01



Antenna Location:




Antenna	Length	Width
WWAN Antenna (Tx / Rx)	5.3 cm	1.3 cm
WLAN & Bluetooth (Tx / Rx)	1.7 cm	0.4 cm
EUT	13.4 cm	7.0 cm

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUTANK45 Page Number : D2 of D2
Report Issued Date : Jan. 21, 2013
Report Version : Rev. 01



Appendix E. Test Setup Photos




Little Barrier Barrier

Right Cheek









Left Tilted



Front of the DUT with Phantom 1 cm Gap



Back of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUTANK45 Page Number : E1 of E1
Report Issued Date : Jan. 21, 2013
Report Version : Rev. 01







Left Side of the DUT with Phantom 1 cm Gap

Right Side of the DUT with Phantom 1 cm Gap







Bottom Side of the DUT with Phantom 1 cm Gap

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUTANK45 Page Number : E2 of E2
Report Issued Date : Jan. 21, 2013
Report Version : Rev. 01