


Report No.: FA3D1804


Appendix D. SAR Test Setup Photos






Right Cheek

Right Tilted





Left Cheek

Left Tilted





Front, Test Separation 1 cm

Back, Test Separation 1 cm

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO55S Page Number : D1 of D2
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01





Left Side, Test Separation 1 cm



Report No.: FA3D1804

Bottom Side, Test Separation 1 cm



Top Side, Test Separation 1 cm



Right Side, Test Separation 1 cm

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO55S Page Number : D2 of D2 Report Issued Date: Jan. 13, 2014 : Rev. 01

Report Version