


Appendix D. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDS45 Page Number : D1 of D2
Report Issued Date : Jun. 17, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.3

Report No.: FR651204B




<Radiated Emission> X Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDS45 Page Number : D2 of D2
Report Issued Date : Jun. 17, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.3

Report No.: FR651204B