

Report No. : FA362605


Appendix D. Test Setup Photos






Right Cheek

Right Tilted





Left Cheek

Left Tilted

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEVIEW Page Number : D1 of D2
Report Issued Date : Jul. 17, 2013
Report Version : Rev. 01









Report No. : FA362605

Front of the DUT with Phantom 1 cm Gap

Back of the DUT with Phantom 1 cm Gap





Bottom Side of the DUT with Phantom 1 cm Gap

Right Side of the DUT with Phantom 1 cm Gap







Top Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEVIEW Page Number : D2 of D2 Report Issued Date: Jul. 17, 2013 Report Version : Rev. 01