Appendix A. Setup Photographs

<Conducted Emission>

Mode 2



Mode 4



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUNEOX Page Number : A1 of A2
Report Issued Date : Mar. 04, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.2

Report No. : FC612802

<Radiated Emission>

Mode 4

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUNEOX Page Number : A2 of A2
Report Issued Date : Mar. 04, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.2

Report No. : FC612802