

# Appendix D. Product Photos




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35 Page Number : D1 of D2
Report Issued Date : Sep. 26, 2012
Report Version : Rev. 01

Report No.: FA291002



### Report No. : FA291002

### **Antenna Location:**



Antenna	Length	Width
WWAN Antenna (Tx / Rx)	5.5 cm	2.0 cm/1.1 cm
Bluetooth & WLAN Antenna (Tx / Rx)	2.6 cm	0.5 cm
EUT	11.5 cm	6.1 cm

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35 Page Number : D2 of D2
Report Issued Date : Sep. 26, 2012
Report Version : Rev. 01



## Report No.: FA291002

#### Appendix E. **Test Setup Photos**



**Right Cheek** 

**Right Tilted** 







**Left Tilted** 



Front of the DUT with Phantom 1 cm Gap




Back of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35 Page Number : E1 of E2 Report Issued Date: Sep. 26, 2012 Report Version : Rev. 01











Report No.: FA291002

Right Side of the DUT with Phantom 1 cm Gap



**Bottom Side of the DUT with Phantom 1 cm Gap** 



Back of the DUT with Phantom 1 cm Gap (with Headset)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35 Page Number : E2 of E2
Report Issued Date : Sep. 26, 2012
Report Version : Rev. 01