


Appendix B. Setup Photographs

<Conducted Emission>

Mode 1~2



Mode 3



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDEEJAYII Page Number : B1 of B3
Report Issued Date : Jun. 10, 2011
Report Version : Rev. 01


Report No. : FD141403






<Radiated Emission>

Mode 1~2





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDEEJAYII Page Number : B2 of B3
Report Issued Date : Jun. 10, 2011
Report Version : Rev. 01

Report No.: FD141403





Mode 3



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDEEJAYII Page Number : B3 of B3
Report Issued Date : Jun. 10, 2011
Report Version : Rev. 01

Report No.: FD141403