

Report No.: FR1D0807

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSWING Page Number : B1 of B2
Report Issued Date : Dec. 15, 2011
Report Version : Rev. 01





Report No.: FR1D0807

<Radiated Emission>



LF



HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSWING Page Number : B2 of B2
Report Issued Date : Dec. 15, 2011
Report Version : Rev. 01