

Report No.: FA221604

Appendix D. Product Photos






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUCHARLESTC Page Number : D1 of D1
Report Issued Date : Feb. 29, 2012
Report Version : Rev. 01



Report No.: FA221604


Appendix E. Test Setup Photos





Right Cheek

Right Tilted






Left Cheek

Left Tilted





Face of the DUT with Phantom 1.5 cm Gap

Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUCHARLESTC Page Number : E1 of E1
Report Issued Date : Feb. 29, 2012
Report Version : Rev. 01