
# Appendix A. Setup Photographs

### <Conducted Emission>

### Mode 2



Mode 3




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO5 Report No.: FC610605-01

Report Template No.: BU5-FC15B Version 1.1

# <Radiated Emission>

### Mode 2

LF



HF



## SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO5 Page Number : A2 of A3
Report Issued Date : Feb. 18, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.1

Report No. : FC610605-01

Report No. : FC610605-01

### Mode 3

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO5 Page Number : A3 of A3
Report Issued Date : Feb. 18, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.1