


Appendix C. Setup Photographs

<Conducted Emission>



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASHL2 Page Number : C1 of C2
Report Issued Date : May 11, 2016
Report Version : Rev. 01

Report No.: FR632501B


Report Template No.: BU5-FR15CBT4.0 Version 1.3




<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASHL2 Page Number : C2 of C2
Report Issued Date : May 11, 2016
Report Version : Rev. 01

Report No.: FR632501B

Report Template No.: BU5-FR15CBT4.0 Version 1.3