

Report No.: FA1D2103

Appendix D. Product Photos






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUHERO Page Number : D1 of D1
Report Issued Date : Jan. 16, 2012
Report Version : Rev. 01



Report No.: FA1D2103

Appendix E. **Test Setup Photos**





Right Cheek



Right Tilted




Left Cheek



Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUHERO

Page Number : E1 of E1 Report Issued Date: Jan. 16, 2012 Report Version : Rev. 01