


Appendix B. Setup Photographs

<Radiated Emission>

E1 Plane

LF



HF



TEL: +86-755- 3320-2398 FCC ID: YHLBLUSTUDIO50S Page Number : B1 of B2
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01


Report No.: FG332505






H Plane

LF



HF



TEL: +86-755- 3320-2398 FCC ID: YHLBLUSTUDIO50S Page Number : B2 of B2
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: FG332505