
1. External Photograph of EUT

Brand Name: BLU; Model Name: Studio 5.0 S II

Report No.: EP411002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 1 of 23




Report No.: EP411002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 2 of 23

Report No.: EP411002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 3 of 23

Report No.: EP411002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 4 of 23

Report No.: EP411002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 5 of 23

Report No.: EP411002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 6 of 23

2. Photograph of Accessory

Brand Name: BLU; Model Name: Studio 5.0 S II

Report No.: EP411002

List of Accessory:

Specification of Accessory		
IAC Adanter	Brand Name	BLU
	Model Name	US-AH-1000
IRattery	Brand Name	BLU
	Model Name	C765804200L
USB Cable	Signal Line Type	1.01m, shielded cable, without core
Earphone	Signal Line Type	1.20m, unshielded cable

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 7 of 23
Report Issued Date : Mar. 04, 2014

Report Version : Rev. 01

Report No.: EP411002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 8 of 23


Report No.: EP411002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 9 of 23



Report No.: EP411002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 10 of 23 Report Issued Date : Mar. 04, 2014

Report Version : Rev. 01