
Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 3



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID : YHLBLUDIVAFLEX Page Number : A1 of A3 Report Issued Date: Jan. 07, 2016 Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.2

Report No.: FC5N1301


<Radiated Emission>

Mode 1

LF







TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDIVAFLEX Page Number : A2 of A3
Report Issued Date : Jan. 07, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.2

Report No.: FC5N1301

C Test Report No. : FC5N1301

Mode 3

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDIVAFLEX Page Number : A3 of A3
Report Issued Date : Jan. 07, 2016
Report Version : Rev. 01
Report Template No.: BU5-FC15B Version 1.2