

# Appendix D. Product Photos





Report No.: FA2D1808



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO465 Page Number : D1 of D2
Report Issued Date : Jan. 04, 2013
Report Version : Rev. 01



Report No.: FA2D1808

### **Antenna Location:**



| Antenna                                  | Length  | Width  |
|--|---------|--------|
| WWAN Antenna <tx rx=""></tx>             | 3.7 cm  | 1.0 cm |
| WLAN & Bluetooth Antenna <tx rx=""></tx> | 1.6 cm  | 1.0 cm |
| EUT                                      | 13.5 cm | 7.0 cm |

| The shortest distance between the Tx antennas |         |  |
|---|---------|--|
| WWAN Antenna to WLAN & Bluetooth Antenna      | 11.1 cm |  |

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO465 Page Number : D2 of D2
Report Issued Date : Jan. 04, 2013
Report Version : Rev. 01



## Report No.: FA2D1808

# Appendix E. Test Setup Photos





**Right Cheek** 







Left Cheek

**Left Tilted** 





Front of the DUT with Phantom 1 cm Gap

Front of the DUT with Phantom 1 cm Gap (w/headset)

## SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO465 Page Number : E1 of E2
Report Issued Date : Jan. 04, 2013
Report Version : Rev. 01



Back of the DUT with Phantom 1 cm Gap



Report No.: FA2N0901

Back of the DUT with Phantom 1 cm Gap (w/headset)



Left Side of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO465 Page Number : E2 of E2
Report Issued Date : Jan. 04, 2013
Report Version : Rev. 01