3. Internal Photograph of EUT

Brand Name: BLU; Model Name: Studio 5.0 S II

Report No.: EP411002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 11 of 23
Report Issued Date : Mar. 04, 2014
Report Version : Rev. 01




Report No.: EP411002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 12 of 23 Report Issued Date : Mar. 04, 2014 Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 13 of 23
Report Issued Date : Mar. 04, 2014
Report Version : Rev. 01

Report No.: EP411002


Brand Name: BLU; Model Name: Studio 5.0 S II



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 14 of 23
Report Issued Date : Mar. 04, 2014
Report Version : Rev. 01



Report No.: EP411002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII

: 15 of 23 Page Number Report Issued Date : Mar. 04, 2014

Report Version : Rev. 01



Report No.: EP411002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 16 of 23
Report Issued Date : Mar. 04, 2014

: Rev. 01

Report Version




Report No.: EP411002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 17 of 23 Report Issued Date : Mar. 04, 2014

Report Version : Rev. 01


Report No.: EP411002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 18 of 23
Report Issued Date : Mar. 04, 2014
Report Version : Rev. 01



Report No.: EP411002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 19 of 23 Report Issued Date : Mar. 04, 2014 Report Version : Rev. 01

Report No.: EP411002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 20 of 23
Report Issued Date : Mar. 04, 2014
Report Version : Rev. 01

Report No.: EP411002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 21 of 23
Report Issued Date : Mar. 04, 2014

Report Version : Rev. 01



Report No.: EP411002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 22 of 23 Report Issued Date : Mar. 04, 2014

: Rev. 01 Report Version



Report No.: EP411002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : 23 of 23 Report Issued Date : Mar. 04, 2014

Report Version : Rev. 01