

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUBROOKLYN Page Number : B1 of B2
Report Issued Date : Dec. 10, 2012
Report Version : Rev. 01

Report No.: FR2N0504A




<Radiated Emission>

Low Frequency



High Frequency



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUBROOKLYN Page Number : B2 of B2
Report Issued Date : Dec. 10, 2012
Report Version : Rev. 01

Report No.: FR2N0504A