
# Appendix A. Setup Photographs


<Radiated Emission>

Y Plane for 22H

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEXL Page Number : A1 of A3
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01

Report No.: FG5O1502A




## Z Plane for 24E

LF



HF




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEXL Page Number : A2 of A3
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01


Report No. : FG5O1502A

## Y Plane for 27L

LF



### HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID : YHLBLULIFEXL Page Number : A3 of A3 Report Issued Date: Dec. 02, 2015 Report Version : Rev. 01

Report No. : FG5O1502A