


## Appendix D. Setup Photographs

## <Conducted Emission>



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASHL2 Page Number : D1 of D2
Report Issued Date : May 11, 2016
Report Version : Rev. 01

Report No.: FR632501C


Report Template No.: BU5-FR15CWL Version 1.3




## <Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASHL2 Page Number : D2 of D2
Report Issued Date : May 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.3

Report No.: FR632501C