# Appendix A. Setup Photographs

# <Conducted Emission>

#### Mode 2



Mode 3




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOCAM Page Number : A1 of A3
Report Issued Date : May 14, 2015
Report Version : Rev. 01

Report No.: FC532407


# <Radiated Emission>

#### Mode 2

LF



### HF




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOCAM Page Number : A2 of A3
Report Issued Date : May 14, 2015
Report Version : Rev. 01

Report No.: FC532407

Report No.: FC532407

# Mode 3

LF



#### HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOCAM Page Number : A3 of A3
Report Issued Date : May 14, 2015
Report Version : Rev. 01