## 3. Internal Photograph of EUT

Brand Name: BLU; Model Name: STUDIO 7.0 II


Report No.: EP570301



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : 12 of 30
Report Issued Date : Sep. 10, 2015
Report Version : Rev. 01



Report No.: EP570301



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : 13 of 30 Report Issued Date : Sep. 10, 2015 : Rev. 01 Report Version




Report No.: EP570301



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : 14 of 30 Report Issued Date : Sep. 10, 2015 : Rev. 01 Report Version



Report No.: EP570301




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II

: 15 of 30 Page Number Report Issued Date : Sep. 10, 2015 Report Version : Rev. 01




Report No.: EP570301



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II

: 16 of 30 Page Number Report Issued Date : Sep. 10, 2015 Report Version : Rev. 01


Report No.: EP570301



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : 17 of 30
Report Issued Date : Sep. 10, 2015
Report Version : Rev. 01




Report No.: EP570301




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : 18 of 30 Report Issued Date : Sep. 10, 2015 Report Version : Rev. 01




Report No.: EP570301



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : 19 of 30 Report Issued Date : Sep. 10, 2015 Report Version : Rev. 01




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : 20 of 30
Report Issued Date : Sep. 10, 2015
Report Version : Rev. 01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : 21 of 30
Report Issued Date : Sep. 10, 2015
Report Version : Rev. 01




Report No.: EP570301




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II

: 22 of 30 Page Number Report Issued Date : Sep. 10, 2015 Report Version : Rev. 01




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : 23 of 30
Report Issued Date : Sep. 10, 2015
Report Version : Rev. 01




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : 24 of 30
Report Issued Date : Sep. 10, 2015
Report Version : Rev. 01

Report No.: EP570301




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : 25 of 30
Report Issued Date : Sep. 10, 2015
Report Version : Rev. 01

Report No.: EP570301




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : 26 of 30
Report Issued Date : Sep. 10, 2015
Report Version : Rev. 01

Report No.: EP570301



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : 27 of 30
Report Issued Date : Sep. 10, 2015
Report Version : Rev. 01


Report No.: EP570301



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : 28 of 30
Report Issued Date : Sep. 10, 2015
Report Version : Rev. 01



Report No.: EP570301




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II

: 29 of 30 Page Number Report Issued Date : Sep. 10, 2015 Report Version : Rev. 01



Report No.: EP570301



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II

: 30 of 30 Page Number Report Issued Date : Sep. 10, 2015 Report Version : Rev. 01