

Appendix B. Setup Photographs

<Conducted Emission>



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPARK Page Number : B1 of B2
Report Issued Date : Oct. 28, 2011
Report Version : Rev. 01


Report No.: FD191701






Report No. : FD191701

<Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPARK Page Number : B2 of B2
Report Issued Date : Oct. 28, 2011
Report Version : Rev. 01