


**Report No. : FA422801** 


## Appendix D. SAR Test Setup Photos





**Right Cheek** 

Right Tilted





Left Cheek

**Left Tilted** 

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUST60HD Page Number : D1 of D2
Report Issued Date : Mar. 19, 2014

Report Version : Rev. 01





Left Side, Test Separation 1 cm



**Report No. : FA422801** 


**Bottom Side, Test Separation 1 cm** 




Top Side, Test Separation 1 cm



Right Side, Test Separation 1 cm



Front, Test Separation 1 cm



Back, Test Separation 1 cm

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUST60HD Page Number : D2 of D2 Report Issued Date: Mar. 19, 2014

Report Version : Rev. 01