

Report No. : FA381615

Appendix D. Test Setup Photos





Right Cheek

Right Tilted





Left Cheek

Left Tilted

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: 86-029-8860-8767

FCC ID:错误!未找到引用源。

Page Number : D1 of D2
Report Issued Date : Sep. 19, 2013

Report Version : Rev. 01





Report No. : FA381615

Front of the DUT with Phantom 1 cm Gap

Back of the DUT with Phantom 1 cm Gap







Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONA (XI'AN) INC.

TEL: 86-029-8860-8767

FCC ID: 错误!未找到引用源。

Page Number : D2 of D2
Report Issued Date : Sep. 19, 2013

Report Version : Rev. 01