


Appendix D. Product Photos







Report No.: FA172805



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDECOMN Page Number : D1 of D2
Report Issued Date : Sep. 14, 2011
Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDECOMN


: D2 of D2 Page Number Report Issued Date: Sep. 14, 2011 Report Version : Rev. 01

Report No. : FA172805



Report No. : FA172805

Appendix E. **Test Setup Photos**



Right Cheek

Right Tilted







Left Tilted







Bottom of the DUT with Phantom 1.5 cm Gap

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDECOMN Page Number : E1 of E1 Report Issued Date: Sep. 14, 2011 Report Version : Rev. 01