

Report No.: FA192002

Appendix D. Product Photos





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJTOUCH Page Number : D1 of D2
Report Issued Date : Oct. 17, 2011
Report Version : Rev. 01



Report No.: FA192002

Appendix E. Test Setup Photos





Right Cheek









Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJTOUCH Page Number : E1 of E1
Report Issued Date : Oct. 17, 2011
Report Version : Rev. 01