


Report No.: FG130433

Appendix B. Setup Photographs


<Conducted Measurement>






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUMAGIC Page Number : B1 of B2
Report Issued Date : May 06, 2011
Report Version : Rev. 01





<Radiated Emission>



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUMAGIC Page Number : B2 of B2
Report Issued Date : May 06, 2011
Report Version : Rev. 01

Report No.: FG130433