

Report No.: FC2D2705

# Appendix B. Setup Photographs

# <Conducted Emission>

### Mode 1



Mode 4



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUARIA

: B1 of B3 Page Number Report Issued Date: Feb. 25, 2013 Report Version : Rev. 01






# <Radiated Emission>

### Mode 2

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUARIA Page Number : B2 of B3
Report Issued Date : Feb. 25, 2013
Report Version : Rev. 01


Report No.: FC2D2705






Mode 4

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUARIA Page Number : B3 of B3
Report Issued Date : Feb. 25, 2013
Report Version : Rev. 01

Report No.: FC2D2705