
Appendix A. Setup Photographs

<Conducted Emission>

Mode 3





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUPUREVIEW Page Number : A1 of A3
Report Issued Date : Dec. 06, 2017
Report Version : Rev. 01

Report No. : FC7O1304

Report Template No.: BU5-FC15B Version 1.3





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUPUREVIEW Page Number : A2 of A3 Report Issued Date : Dec. 06, 2017 Report Version : Rev. 01

Report No.: FC7O1304

Report Template No.: BU5-FC15B Version 1.3

<Radiated Emission>

Mode 5

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUPUREVIEW Page Number : A3 of A3
Report Issued Date : Dec. 06, 2017
Report Version : Rev. 01

Report No.: FC7O1304

Report Template No.: BU5-FC15B Version 1.3