

## Appendix B. Setup Photographs

## <Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTATTOOS Page Number : B1 of B2
Report Issued Date : Mar. 20, 2013
Report Version : Rev. 01

Report No.: FR322204




Report No. : FR322204

## <Radiated Spurious Emission>

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTATTOOS Page Number : B2 of B2
Report Issued Date : Mar. 20, 2013
Report Version : Rev. 01