


Report No.: FR870301B

Appendix E. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXI


Page Number : E1 of E2 Report Issued Date Jul. 23, 2018 Report Version : Rev. 01 Report Template No.: BU5-FR15CBT4.0 Version 2.0




<Radiated Emission>

Z Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXI Page Number : E2 of E2
Report Issued Date Jul. 23, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0 Version 2.0

Report No.: FR870301B