


Report No.: FR052523


Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLCTBLUTATTOO Page Number : B1 of B4
Report Issued Date : Jun. 25, 2010
Report Version : Rev. 01





Report No.: FR052523



Side View


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLCTBLUTATTOO Page Number : B2 of B4
Report Issued Date : Jun. 25, 2010
Report Version : Rev. 01






<Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLCTBLUTATTOO Page Number : B3 of B4
Report Issued Date : Jun. 25, 2010
Report Version : Rev. 01

Report No.: FR052523





Report No.: FR052523



Remote View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLCTBLUTATTOO Page Number : B4 of B4
Report Issued Date : Jun. 25, 2010
Report Version : Rev. 01