


## Appendix D. Setup Photographs

## <Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUPUREVIEW Page Number D1 of D2
Report Issued Date : Dec. 06, 2017
Report Version : Rev. 01

Report No.: FR7O1304C

Report Template No.: BU5-FR15CWL Version 2.0




## <Radiated Emission>

## **Z** Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUPUREVIEW Page Number D2 of D2
Report Issued Date : Dec. 06, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 2.0

Report No.: FR7O1304C