
## **Appendix C. Setup Photographs**


## <Radiated Emission>

Z Plane for 22H

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOTCH Page Number : C1 of C3
Report Issued Date : May 13, 2016

Report No.: FG640701A


Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.1



## Z Plane for 24E

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOTCH Page Number : C2 of C3
Report Issued Date : May 13, 2016

Report No. : FG640701A


Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.1




## Y Plane for 27L

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOTCH Page Number : C3 of C3
Report Issued Date : May 13, 2016

Report No. : FG640701A

Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.1