# Appendix A. Setup Photographs

### <Conducted Emission>

#### Mode 2



Mode 3




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDIVAFLX24 Page Number : A1 of A3
Report Issued Date : Oct. 29, 2015
Report Version : Rev. 01

Report No.: FC592509

## <Radiated Emission>

### Mode 2

LF



HF




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDIVAFLX24 Page Number : A2 of A3
Report Issued Date : Oct. 29, 2015
Report Version : Rev. 01


Report No.: FC592509

# Mode 3

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDIVAFLX24 Page Number : A3 of A3
Report Issued Date : Oct. 29, 2015
Report Version : Rev. 01

Report No.: FC592509