


Appendix C. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOTCH Page Number : C1 of C2
Report Issued Date : May 13, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0 Version 1.3


Report No.: FR640701B



<Radiated Emission>

X Plane

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOTCH Page Number : C2 of C2
Report Issued Date : May 13, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3

Report No.: FR640701B