3. Internal Photograph of EUT

Brand Name: BLU; Model Name: Studio 6.0 HD

Report No.: EP422801



TEL: 86-755- 3320-2398 FCC ID: YHLBLUST60HD Page Number : 12 of 29
Report Issued Date : Mar. 19, 2014
Report Version : Rev. 01



Report No.: EP422801



TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD

: 13 of 29 Page Number Report Issued Date : Mar. 19, 2014 Report Version : Rev. 01

Report No.: EP422801




TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD Page Number : 14 of 29
Report Issued Date : Mar. 19, 2014
Report Version : Rev. 01

Report No.: EP422801




TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD Page Number : 15 of 29
Report Issued Date : Mar. 19, 2014
Report Version : Rev. 01

Report No.: EP422801



TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD Page Number : 16 of 29
Report Issued Date : Mar. 19, 2014
Report Version : Rev. 01


Report No.: EP422801



TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD Page Number : 17 of 29 Report Issued Date : Mar. 19, 2014

Report Version : Rev. 01






SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD Page Number : 18 of 29
Report Issued Date : Mar. 19, 2014
Report Version : Rev. 01






Report No.: EP422801



TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD Page Number : 19 of 29
Report Issued Date : Mar. 19, 2014
Report Version : Rev. 01




Report No.: EP422801




TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD Page Number : 20 of 29
Report Issued Date : Mar. 19, 2014
Report Version : Rev. 01

Report No.: EP422801



TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD Page Number : 21 of 29
Report Issued Date : Mar. 19, 2014
Report Version : Rev. 01


Report No.: EP422801



TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD Page Number : 22 of 29
Report Issued Date : Mar. 19, 2014
Report Version : Rev. 01




Report No.: EP422801



TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD Page Number : 23 of 29 Report Issued Date : Mar. 19, 2014 Report Version : Rev. 01





SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD Page Number : 24 of 29
Report Issued Date : Mar. 19, 2014
Report Version : Rev. 01

Report No.: EP422801



TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD Page Number : 25 of 29
Report Issued Date : Mar. 19, 2014
Report Version : Rev. 01

Report No.: EP422801




TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD Page Number : 26 of 29 Report Issued Date : Mar. 19, 2014

Report Version : Rev. 01




Report No.: EP422801



TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD Page Number : 27 of 29 Report Issued Date : Mar. 19, 2014 Report Version : Rev. 01



Report No.: EP422801




TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD

: 28 of 29 Page Number Report Issued Date : Mar. 19, 2014 Report Version : Rev. 01



Report No.: EP422801



TEL: 86-755-3320-2398 FCC ID: YHLBLUST60HD Page Number : 29 of 29
Report Issued Date : Mar. 19, 2014
Report Version : Rev. 01