

Report No.: FR1O2501A

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUELECTRO Page Number : B1 of B2
Report Issued Date : Nov. 30, 2011
Report Version : Rev. 01






LF

Report No. : FR1O2501A

<Radiated Emission>



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUELECTRO Page Number : B2 of B2
Report Issued Date : Nov. 30, 2011
Report Version : Rev. 01