
# Appendix A. Setup Photographs

## <Conducted Emission>

### Mode 2



Mode 3




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : A1 of A3
Report Issued Date : Sep. 10, 2015
Report Version : Rev. 01

Report No.: FC570301


# <Radiated Emission>

### Mode 1

LF



HF




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : A2 of A3
Report Issued Date : Sep. 10, 2015
Report Version : Rev. 01

Report No.: FC570301


Report No.: FC570301

## Mode 3

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : A3 of A3
Report Issued Date : Sep. 10, 2015
Report Version : Rev. 01