
3. Internal Photograph of EUT

Brand Name: BLU; Model Name: Dash 3.5 II

Report No.: EP4O0904



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II Page Number : 12 of 23
Report Issued Date : Nov. 18, 2014
Report Version : Rev. 01



Report No.: EP4O0904



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II

: 13 of 23 Page Number Report Issued Date : Nov. 18, 2014 Report Version : Rev. 01




Report No.: EP4O0904



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II Page Number : 14 of 23 Report Issued Date : Nov. 18, 2014 Report Version : Rev. 01




Report No.: EP4O0904



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II Page Number : 15 of 23 Report Issued Date : Nov. 18, 2014 Report Version : Rev. 01




Report No.: EP4O0904



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II Page Number : 16 of 23 Report Issued Date : Nov. 18, 2014 : Rev. 01 Report Version

Report No.: EP400904




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II Page Number : 17 of 23
Report Issued Date : Nov. 18, 2014
Report Version : Rev. 01




Report No.: EP4O0904



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II Page Number : 18 of 23 Report Issued Date : Nov. 18, 2014 Report Version : Rev. 01

Report No.: EP4O0904




SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II Page Number : 19 of 23 Report Issued Date : Nov. 18, 2014

Report Version : Rev. 01


Report No.: EP4O0904




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II Page Number : 20 of 23
Report Issued Date : Nov. 18, 2014
Report Version : Rev. 01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II Page Number : 21 of 23
Report Issued Date : Nov. 18, 2014
Report Version : Rev. 01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II