


Report No.: FA332505

Appendix D. **Test Setup Photos**





Right Cheek

Right Tilted





Left Cheek

Left Tilted


SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO50S Page Number : D1 of D3 Report Issued Date: Apr. 19, 2013

Report Version : Rev. 01







Front of the DUT with Phantom 1cm Gap



Report No.: FA332505

Back of the DUT with Phantom 1 cm Gap



Back of the DUT with Phantom 1 cm Gap (with / Headset)



Left Side of the DUT with Phantom 1 cm Gap

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO50S Page Number : D2 of D3 Report Issued Date : Apr. 08, 2013 Report Version : Rev. 01







Report No.: FA332505

Right Side of the DUT with Phantom 1 cm Gap

Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO50S