


### Report No.:FR651207A

# Appendix B. Setup Photographs

# <Conducted Emission>



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTDC88LTE Page Number : B1 of B2
Report Issued Date : Jun. 20, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1




## Report No. :FR651207A


# <Radiated Emission>

### Z Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTDC88LTE Page Number : B2 of B2
Report Issued Date : Jun. 20, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1