
Appendix A. Setup Photographs

<Conducted Emission>

Mode 6





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLULIFEONEX3 Page Number : B1 of B3
Report Issued Date : Sep. 30, 2017
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No.: FC790406


<Radiated Emission>

Mode 5

LF



HF



Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLULIFEONEX3 Page Number : B2 of B3
Report Issued Date : Sep. 30, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


Report No.: FC790406

Mode 6

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLULIFEONEX3 Page Number : B3 of B3
Report Issued Date : Sep. 30, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC790406